AP-US (Ib version) OWNER'S MANUAL







CONTENTS


RECAUTIONS	4
REFACE	б
NSTALLATIONS	6
IAMES AND FUNCTIONS	7
PERATIONS	
I. General Weighing	9
2. Weighing with Tare	10
3. 1/2 Key	- 12
1. 1/4 Key	13
5. Prepack	13
5. Taresave	14
7. Add key	· 14
3. How to Call the Added Total Price	15
). Saving a PLU to Memory	16
). How to Call a PLU	18
RROR MESSAGES	19
DECIEICATIONS	วก

PRECAUTIONS

Make sure that you plug your scale into the proper power outlet. Plug into a power outlet 30 minutes before operations.











The socket-outlet shall be installed near the equipment and shall be easily accessible.



■ If the scale is not properly level, please adjust the 4 legs at the bottom of the scale (turn legs clockwise or counterclockwise) so as to center the bubble of the leveling gauge inside the indicated circle.



5

PREFACE


Thank you for the purchasing of our CAS AP Series.

These series had been designed with CAS reliability, under rigid quality control and with outstanding performance. Your departments can enjoy with this high quality reliable CAS product.

We believe that your needs will be satisfied and you will have proper reliability. This manual will help you with proper operations and take care of the AP series. Please keep it handy for the future references.


INSTALLATIONS

Insert the post pipe into a post bracket as shown in Fig. -1 Screw the post bracket and the post pipe as shown in Fig. -2




NAMES AND FUNCTIONS

OVERALL VIEW



DISPLAY & KEYBOARD




■ KEY FUNCTIONS	
KEYS	FUNCTIONS
0~9	Used to enter all the numerical data.
00	Used to enter a double zero.
C	Used to clear erroneous entries and error conditions.
ZERO	Used to correct the zero point.
TARE	Used to enter a tare weight. Used to remove a tare weight.
ON OFF	Turns the displays on or off.
1/2	Used to convert a unit price to a half pound.
1/4	Used to convert a unit price to a quarter pound.
PRE	Used to prevent the auto clearing of unit price.
TARE	Used to prevent the auto clearing of tare weight.
ADD	Used to add up prices of weighed items.
TTP	Used to recall the total price of add up transactions.
MR	Used to call an indirect PLU(Price Look Up).
MW	Used to store a PLU(Price Look Up) to memory.
*	No function key.

OPERATIONS

- When you turn on the power, the scale will count "00000" to "99999". Then the scale will read "0.000" in the weight display. This is called the ZERO state.
- If the scale is not ZERO state though there is nothing on the platter, press the ZERO key.
- The display indicates if the scale is at ZERO or if there is a TARE entered into the scale by way of a ZERO and NET lamps.

1. General Weighing




the platter.

from the platter.


▶ NOTE: The unit price is cleared automatically after each transaction.


2. Weighing with Tare


Unknown(weighed) tare

















0.00

MMM 4.44


MMMM



(1) Place the container on the platter.

2 Press the TARE key.

3) Enter a unit price.










4 Place commodity on the platter.




(5) Remove commodity from the platter.

Known(manually entered) tare














(1) Enter tare weight by pressing the numeric key.

2 Press the TARE key.

(3) Place the container and enter a unit price.







FIFT 444




platter.

(5) Remove commodity and container from the platter.

▶ NOTE 1: The tare is cleared automatically after each transaction.


3. 1/2 Key



- ① Enter a unit price.
- 2) Press 1/2 key. This function doubles the unit price.
- Place the commodity on the platter.



4 Remove the commodity from the platter.



- () Enter a unit price.
- ② Press 1/4 key. This function quadruples the unit price.
- ③ Place the commodity on the platter.



Remove the commodity from the platter.

5. Prepack

The PREPACK key is used to prevent the auto clearing of unit price. To use this function, just press the PREPACK key before you call a PLU. While "PRE PACK" is activated, the unit price is fixed unless you press the "C" key.

To release this function, press the "PRE PACK" key again.

■ The display indicates if the PREPACK is activated by way of a PREPACK lamp.

, die

6. Taresave

The TARESAVE key is used to prevent the auto clearing of tare weight.

To use this function, just press the TARESAVE kev.


While "TARE SAVE" is activated, tare values are fixed unless you press the "TARE" key.

To release this function, press the "TARE SAVE" key again.

■ The display indicates if the TARESAVE is activated by way of a TARE lamp.


7. Add key

You can add up 99 items up to \$9999.99, otherwise you will hear a beep. You can see the total price by pressing TTP CALL key.



another commodity.


the platter.



8. How to Call the Added Total Price

This function is used in conjunction with the "ADD" key. "TTP CALL" key shows the total price of all the added items.


To display the total price of added commodities



return to weighing mode.

from the platter.

To clear the total price of added commodities




- () Press TTP CALL key.
- ② Press C key to clear total price and return to weighing mode.

9. Saving a PLU to Memory

This scale has 28 direct PLUs and 172 indirect PLUs.

A) For Direct PLUs

(1) Enter a unit price.



2 Press MW key.

(3) Press one of the direct PLU

keys.

- B) For Indirect PLUs

 3.75

 3.75

 3.75

 4.75

 5.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.75

 6.
 - ③ Enter a desired address number of the PLU.

NOTE: The address number of the PLU is limited from 0 to 199

0.00

0.00

0.000


C> MW

4) Press MW key.

10. How to Call a PLU

Make sure that the platter is empty when you call a PLU

A) For Direct PLUs



- D Press one of the direct PLU keys.
- 2) Place the commodity on the platter.
- ③ Remove the commodity from the platter.

B) For Indirect PLUs



- ① Enter the address of an indirect PLU.
- 2) Press MR key.
- 3) **Place a commodity on th**
- 3) Place a commodity on the platter.



- 4 Remove the commodity from the platter.
- ▶ NOTE: Do not use the decimal point while recalling PLUs.

ERROR MESSAGES

To help the customer's understanding, this scale warns the user with proper error message. Please refer to the table below.

ERROR	REASONS	SOLUTIONS
Err 1	An error of the initial zero range	Make sure the platter is empty. Make sure there is a platter on the scale.
Err 6	An overflow has occurred from the ADD key	Press the C key
Err 8	An overflow has occurred in the transaction counter	Press C key
Err 10	Failure of analog module	Call your CAS dealer
Err 11	Failure of digital module	Call your CAS dealer
Err 12	Condition codes are broken	Call your CAS dealer for span calibration
Err 13	Key codes are broken	Call your CAS dealer for span calibration

SPECIFICATIONS

MODEL		AP-1	
CAPACITY	15×0.005lb	30×0.01 lb	60×0.02 lb
DISPLAYS:			
WEIGHT	5 DIGITS	5 DI	GITS
UNIT PRICE	6 DIGITS	4 DI	GITS
TOTAL PRICE	6 DIGITS	4 DI	GITS
MAXIMUM TARE	-9.995 lb	-30.00lb	-60.00lb
DISPLAY DESIGNATORS	ZERO, NET, PREPACK, TARESAVE		
	-10℃ ~ +40℃		
POWER SOURCE	AC 120 V / 60 Hz		
POWER CONSUMPTION	APPROX. 10W		
PLATTER SIZE (W×D)	340×215mm/13.4×8.5inch		
PRODUCT SIZE (W \times D \times H)	435×325×495mm/17.1×12.8×19.5inch		
PRODUCT WEIGHT	6.5 kg		

▶ Notice: Specifications are subject to change for improvement without notice.

MEMO

Price Computing Scale AP-US (Ib version)

OWNER'S MANUAL




CONTENTS


PRECAUTIONS 4	
PREFACE 6	,
INSTALLATIONS 6	,
NAMES AND FUNCTIONS 7	1
OPERATIONS9)
1. General Weighing 9)
2. Pricing 1/2 Key)
3. Pricing 1/4 Key 10)
4. Weighing with Tare 10)
5. Saving a Current Tare Weight and Unit Price 12	
6. Saving a Unit PLU to Memory 12	,
7. How to Call a PLU	
8. How to Print	,
ERROR MESSAGE17	!
SPECIFICATIONS17	!

PRECAUTIONS

Precautions when installing the scale. To ensure that you get the most from your scale, please follow these instruction.



The socket-outlet shall be installed near the equipment and shall be easily accessible.



4 5

PREFACE


Thank you for the purchasing of our CAS AP Series.

These series have been designed with CAS reliability, under rigid quality control and with outstanding performances. Your speciality departments can enjoy with these high quality reliable CAS products.

We believe that your needs will be satisfied and you will have proper reliability in variable weight.

This manual will help you with proper operations and take care of the AP series. Please keep it handy for the future references.


INSTALLATIONS




- 1. Loosen the twist lock nut on the display pole as fig. 1.
- 2. Pull the harness wire as fig. 2.
- 3. Turn the post pipe $180\,^\circ$ and insert the projections of post pipe into the holes on the bracket as fig. 3
- 4. Insert and fasten display assembly screws as fig. 1
- 5. Tighten the twist lock nut on the display pole as fig.4

NAMES AND FUNCTIONS

OVERALL VIEW



DISPLAY & KEYBOARD




■ KEY FUNCTIONS

KEYS	FUNCTIONS
0~9	Used to enter all the numerical data.
00	Used to enter a double zeros.
C	Used to clear all the numerics dn the unit price display. Used to clear sum total price.
ZERO	Used to correct the zero point.
TARE	Used to enter a tare weight. Used to delete a tare weight.
1/2	This key allows the sale of items by unit price per half pound.
1/4	This key allows the sale of items by unit price per quarter pound.
MW	Used to store PLU(price look up) to memory up to 499 items.
MR	Used to call PLU(price look up) in memory up to 499 items.
SAVE	Used to saves a current tare and currently called unit price from automatically.
PRINT	Enable or Disable Auto-printing funtion.
	Direct PLU keys.

OPERATIONS


- When you turn on the power, the scale will count "99999" to "00000". Then the scale will read "0.000" in the weight display. This is called the ZERO state.
 - If the scale is not ZERO state though there is nothing on the platter, press the
- The display indicates if the scale is at ZERO or if there is a TARE entered into the scale by way of a ZERO and NET lamps.

1. General Weighing





- ① Enter a unit price.
- ② Place the commodity on the platter.
- (3) Remove the commodity from the platter.
- ▶ NOTE : The unit price is cleared automatically after each weighing

2. Pricing: 1/2 Key



- ① Enter a unit price.
- 2) Press the 1/2 key





① Enter a unit price.


2) Press the 1/4 key

353 ה ה ה ユユコ 7777 2.33 7777 过过过 #/

- (4) Place the commodity on the platter.
- (5) Remove the commodity from the platter.

4. WEIGHING WITH THE TARE

A) Unknown (weighed) tare



- Place the container on the platter.
- ② Press the TARE key.
- (3) Enter a unit price.

וו וו וו

וו וו וו


4.44

4.5.5

(3) This function quadruples the price per pound.

444

B) Known (manually entered) tare



platter and enter a unit price.






- 5) Remove commodity with container from the platter. If you want to save tare weight and unit price, press the SAVE key.

- 4 Place the commodity in the container.
- ▶ NOTE: The tare is cleared automatically after each transaction.

5. SAVING A CURRENT TARE WEIGHT AND UNIT PRICE

The function saves currently called unit price from automatically clearing.



- ① Press the SAVE key. Set the tare weight,1.00lb, and enter a unit price.
- ② Place the commodity on

the platter.


(3) Remove the commodity from the platter. Then the display still shows tare weight, and unit price.

6. SAVING A PLU TO MEMORY

The function saves each PLU into a internal back up memories. The PLU means Price Look Up which has an unit price.


- AP-EX has 28direct PLUs and 200 indirect PLUs.
- AP-MX has 5direct PLUs and 200 indirect PLUs.
- AP-SM has 7direct PLUs.

A) For Direct PLUs




- ① Enter a unit price.
- 2 Press the MW key.
- 3 Press one of the PLU keys.

B) For Indirect PLUs



(0 To 199)

- 1) Enter a unit price.
- 2 Press the MW key.




(4) Press the MW key.



7. How to Call a PLU


Make sure that the platter is empty before call up a PLU.

A) For Direct PLUs




- ① Press one of the direct PLU keys.
- ② Place the commodity on the platter.
- ③ Remove the commodity from the platter.

B) For Indirect PLUs




- ② Press the MR key.
- ③ Place the commodity on the platter.



- Remove the commodity from the platter.
- ▶ NOTE : Decimal point of the unit price display has no meaning.


8. How to Print

Turn print function on.



① Press the PRINT key.

Do general weighing.



- (1) Enter a unit price.
- ② Place commodity on the platter. and then printing is done automatically
- ③ Remove the commodity from the platter.

▶ Example

DATE	
weight unit price No_PLU	total
11.40 lb @ \$3.75/lb	\$42.75
Sum(\$)	\$42.75

ERROR MESSAGES

To help for the customer's understanding, this scale warns the error message properly. Please refer to error table.

ERROR	MEANINGS	SOLUTIONS	
Display	An error of the initial zero range	set the platter empty.	
HELP 1	All error or the illitial zero range	set the platter empty.	
Display	A failure of the analog module	Call your CAS dealer	
ERR 10	A failure of the analog module		
Long Beep	key codes are broken	Call your CAS dealer from calibration	

SPECIFICATIONS

MODEL	AP-1
CAPACITY	030×0.01 lb / 3060×0.02 lb
DISPLAYS:WEIGHT UNIT PRICE TOTAL PRICE	5 DIGIT 6 DIGIT 7 DIGIT
DISPLAY DESIGNATORS	ZERO, TARE, SAVE
MAXIMUM TARE	-29.99 lb
OPERATING TEMPERATURE	-10°C ~ +40°C
POWER SOURCE	AC 120V / 60Hz
POWER CONSUMPTION	APPROX. 10W
PLATTER SIZE (W ×D)	340(W) ×215(D)
PRODUCT SIZE (W ×D ×H)	435(W) ×325(D) ×495(H)

▶ Notice: Specifications are subject to change for improvement without notice.

MEMO