# Masseomparator

# INSTRUCTION MANUAL

**MC-100KS** 



# This Manual and Marks

All safety messages are identified by the following, "WARNING" or "CAUTION", of ANSI Z535.4 (American National Standard Institute: Product Safety Signs and Labels). The meanings are as follows:

<b>⚠</b> WARNING	A potentially hazardous situation which, if not avoided, could result in death or serious injury.
<b>A</b> CAUTION	A potentially hazardous situation which, if not avoided, may result in minor or moderate injury.



This is a hazard alert mark.

- □ This manual is subject to change without notice at any time to improve the product.
- □ The contents of the product specifications and this manual are subject to change without any obligation on the part of the manufacturer.
- Under the copyright laws, the software (program) described in it are copyrighted, with all rights reserved.

The software may be installed into one computer and may not be installed into other computers without the prior written consent of A&D Company. Copying includes translation into another language, reproduction, conversion, photocopy and offer or loan to another person.

- Microsoft, Windows, Word and Excel are registered trademarks of the Microsoft Corporation.
  - © 2016 A&D Company, Limited All rights reserved. No part of this publication may be reproduced, transmitted, transcribed, or translated into any language in any form by any means without the written

permission of A&D Company, Limited.

# Contents

Basic Ope	ration	
1. 1-1. 1-2. 1-3. 1-3-1. 1-3-2.		.3 .4 .4
2. 2-1.	Unpacking And Installing The BalanceInstalling the Balance	
3. 3-1. 3-2. 3-3. 3-4.	Precautions  Before Use  During Use  After Use  Power Supply	.8 .9 10
4.	Display Symbols And Key Operation	11
5.	Weighing Units	12
6. 6-1. 6-2. 6-2-1. 6-2-2. 6-2-3.	3 3	14 14 14 14
Adapting	to the Environment	
7. 7-1. 7-2.	Weighing Speed Adjustment / Self Check Function	16
8. 8-1. 8-2. 8-3. 8-4. 8-5. 8-6.	Calibration Calibration Group Automatic Self Calibration One-Touch Calibration Calibration Using an External Weight Calibration Test Using an External Weight Correcting the Internal Mass Value	18 19 20 21 22
Functions		
9. 9-1. 9-2.	Function Switch And Initialization 2 Permit or Inhibit 2 Initializing the Balance 2	25
10. 10-1. 10-2. 10-3. 10-4. 10-5.	Function Table	27 27 28 32

10-6.	Description of the Item "Data Format"	34
10-6-1		
10-7.	Data Format Examples	37
11.	ID Number And GLP Report	38
11-1.	Setting the ID Number	
11-2.	GLP Report	
RS-232C	Serial Interface	
12.	Standard Input And Output Interface	42
12-1.	RS-232C and External Contact Input	
12-2.	Connection to Peripheral Equipment	
12-2-		
12-2-2	2. Connection to a Computer and the Use of WinCT	45
13.	Commands	46
13-1.	Command List	
13-2.	Acknowledge Code and Error Codes	47
13-3.	Control Using CTS and RTS	
13-4.	Settings Related to RS-232C	48
14.	Extended Function	49
14-1.	Description of "Averaging range" and "Averaging time"	
14-1-	•	
14-1-	2. Filter Depending on Differences in the Amount to Deliver Powdery and Liquid Material.	51
Maintena	nce	
15.	Maintenance	52
15-1.	Treatment of the Balance	52
16.	Troubleshooting	53
16-1.	Checking the Balance Performance and Environment	
16-2.	Error Codes	
16-3.	Other Display	
16-4.	Asking for Repair	
17.	Specifications	57
17. 17-1.	External Dimensions	
17-1. 17-2.	Options and Peripheral Instruments	
18.	Terms/Index	
18-1.	Terms	
18-2.	Index	03

# 1. Introduction

This manual describes how the MC Series Mass Comparator Balance, MC-100KS works and how to get the most out of it in terms of performance.

Read this manual thoroughly before using the balance and keep it at hand for future reference.

For other functions and operations that this manual does not describe, refer to the GP series instruction manual.

## 1-1. About This Manual

This manual consists of the following five parts:

Basic operation .......Describes precautions, the balance's construction and basic

operation.

Adapting to the environment.....Describes response (and stability) adjustment to adapt to the environment where there is vibration or drafts, the way to maintain weighing precision in a variation of ambient temperature, calibration and calibration test.

Selecting functions......Describes functions of the balance.

Interface and communication....Describes the RS-232C serial interface and external contact

input. The RS-232C serial interface can communicate with a computer that requests weighing data and controls the balance. This RS-232C interface is for use with a computer or printer. The external contact input commands the balance

re-zeroing and data output.

Maintenance .................Describes maintenance, error codes, troubleshooting,

specifications and options.

#### 1-2. Features

- Display resolution, one digit greater than a standard balance. This allows management of OIML class M1 or lower weights.
- Capable of weighing small amounts of powdery or liquid material, even with a massive tare.
- Standard RS-232C serial interface to communicate with a computer.
   Windows communication tools software (WinCT) to allow easy communication with a computer using Windows.

The current version of the WinCT can be downloaded from the A&D website.

# 1-3. Compliance

## 1–3–1. Compliance with FCC Rules

Please note that this equipment generates, uses and can radiate radio frequency energy. This equipment has been tested and has been found to comply with the limits of a Class A computing device pursuant to Subpart J of Part 15 of FCC rules. These rules are designed to provide reasonable protection against interference when equipment is operated in a commercial environment. If this unit is operated in a residential area, it may cause some interference and under these circumstances the user would be required to take, at his own expense, whatever measures are necessary to eliminate the interference.

(FCC = Federal Communications Commission in the U.S.A.)

# 1-3-2. Compliance With Directives of CE mark

This device features radio interference suppression, safety regulation and restriction of Hazardous Substances in compliance with the following Council Directives

Council directive 2004/108/EC EN61326 EMC directive

Council directive 2006/95/EC EN60950 Safety of Information Technology Equipment Council directive 2011/65/EU EN50581 Restriction of the use of certain Hazardous

Substances

The CE mark is an official mandatory European marking.
Please note that any electronic product must comply with local laws and regulations when sold or used anywhere outside Europe.



A&D INSTRUMENTS LTD
24 Blacklands Way
Abingdon Business Park,
Ahingdon, Oxford,
OX14 1DY United Kingdom
Phone: +44 [0]1235 550420
Fax: +44 (0)1235 550485
VAT Reg no. GB 596 1273 15
UK Reg. Office No. 2609110

# CE

A & D Instruments Ltd. hereby declare that the following Weighing product conforms to the requirements of the council directives on ...

Electromagnetic Compatibility (EMC) 2004/108/EC, Low Voltage Equipment (LVD) 2006/95/EC amended by 93/68/EEC and Restriction of the use of certain Hazardous Substances (RoHS) 2011/65/EU

provided that they bear the CE mark of conformity.

Model/Series....MC-100K

Standards applicable:

#### EN 61326-1:2013

Electrical equipment for measurement, control and laboratory use -EMC requirements Part 1: General requirements

EN 60950-1:2006+A11:2009+A1:2010.A11:2012

Safety of Information Technology Equipment

EN 50581:2012

Technical documentation for the assessment of electrical and electronic products with respect to the restriction of hazardous substances

CE Mark first applied 09 November 2010 Signed for A&D Instruments in Oxford England 01 August 2015

P. Argus Managing Director

AD








# 2. Unpacking And Installing The Balance

- The balance is a precision instrument. Unpack the balance carefully. Keep the packing material to be used for transporting the balance in the future.
- After unpacking, see the illustrations to confirm that everything is included.




Note Please confirm that the AC adapter type is correct for your local voltage and receptacle type.

# 2-1. Installing the Balance

Install the balance as follows:

- 1 Refer to "3. Precautions" for installing the balance.
- 2 Adjust the leveling feet to level the balance. Confirm it using the bubble spirit level.
- 3 Confirm that the AC adapter type is correct for the local voltage and receptacle type.
- 4 Insert the AC adapter firmly into the AC adapter jack on the balance. Ground the balance. Warm up the balance for at least 30 minutes with nothing on the weighing pan.



# 3. Precautions

To get the optimum performance from the balance and acquire accurate weighing data, note the following:


#### 3-1. Before Use


- The maximum resolution of the precision balance is million counts. Therefore, there are tendencies to be influenced by temperature change, air pressure change, static electricity, vibration and drafts where the balance is placed.
- Install the balance in an environment where the temperature and humidity are not excessive.
   The best operating temperature is about 20°C / 68°F at about 50% relative humidity.
- Install the balance where it is not exposed to direct sunlight and it is not affected by heaters or air conditioners.
- Install the balance where it is free of dust.
- Install the balance away from equipment that produces magnetic fields.
- Install the balance in a stable place avoiding vibration and shock. Corners of rooms on the first floor are best, as they are less prone to vibration.
- □ The weighing table should be solid and free from vibration, drafts and as level as possible.
- Level the balance by adjusting the leveling feet and confirm it using the bubble spirit level.
- If static electricity is a problem at the installation site, use the electrostatic field meter and the static eliminator.
- Ensure a stable power source when using the AC adapter.
- Connect the AC adapter and warm up the balance for at least 30 minutes.
- Calibrate the balance periodically for accurate weighing.
- When the balance is installed for the first time or has been moved, warm up the balance for at least 6 hours to allow the balance to reach equilibrium with the ambient temperature, and then perform calibration before use.
- The meaning of IP-65 is "No ingress of dust. Protected against water jets".
  If a powerful water jet is used or the balance is immersed in water, it may cause a damage that is due to ingress of water.
- Confirm that "the AC adapter plug is inserted firmly into the AC adapter jack" and "the RS-232C serial interface terminal is covered using the optional waterproof cover, when using as a waterproof and dustproof balance.
- When performing data transmission using the RS-232C serial interface, the balance does not comply with IP-65 (waterproof and dustproof).


⚠ Do not install the balance where flammable or corrosive gas is present.

# 3–2. During Use

- Discharge static electricity from the weighing material. When weighing sample (plastics, insulator, etc.) could have a static charge, the weighing value is influenced. Ground the balance, and
  - Eliminate the static electricity by using an optinal static eliminator, AD-1683.
  - Or try to keep the ambient humidity above 45%RH at the room.
  - Or use the metal shield case.
  - Or wipe a charged material (plastic sample etc.) with the wet cloth.
- This balance uses a strong magnet as part of the balance assembly, so please use caution when weighing magnetic materials such as iron. If there is a problem, use the underhook on the bottom of the balance to suspend the material away from the influence of the magnet.
- Eliminate any temperature difference between the sample and the environment. When a sample is warmer (cooler) than the ambient temperature, the sample will be lighter (heavier) than the true weight. This error is due to a rising (falling) draft around the sample.
- Make each weighing gently and quickly to avoid errors due to changes in the environmental conditions.
- Do not drop things upon the weighing pan, or place a sample on the pan that is beyond the balance weighing capacity. Place the sample in the center of the weighing pan.
- Do not use a sharp instrument such as a pencil to press the keys. Use your finger only.
- Press the RE-ZERO key before each weighing to prevent possible errors.
- Calibrate the balance periodically so as to eliminate possible errors.
- Take into consideration the affect of air buoyancy on a sample when more accuracy is required.
- The reference card is provided to refer for basic operations.
- Prevent foreign matter, such as powder, liquid and metal, from invading the area around the weighing pan.







#### 3–3. After Use

- Avoid mechanical shock to the balance.
- Do not disassemble the balance. Contact the local A&D dealer if the balance needs service or repair.
- Do not use organic solvents to clean the balance. Clean the balance with a lint free cloth that is moistened with warm water and a mild detergent.
- Do not allow the balance to be immersed in water. Even though the balance complies with IP code, the balance will not withstand being completely immersed in water.
- □ The weighing pan can be removed to clean the balance. Clean by splashing with water.

# 3–4. Power Supply


- Do not remove the AC adapter while the internal mass is in motion, for example, immediately after the AC adapter is connected, or during calibration using the internal mass.
  - If the AC adapter is removed under the conditions described above, the internal mass will be left unsecured, that may cause mechanical damage when the balance is moved. Before removing the AC adapter, press the ON:OFF key and confirm that zero is displayed.
- When the AC adapter is connected, the balance is in the standby mode if the standby indicator is on. This is a normal state and does not harm the balance. For accurate weighing, keep the AC adapter connected to the balance unless the balance is not to be used for a long period of time.


# 4. Display Symbols And Key Operation

#### **Key Operations**

Key operation affects how the balance functions. The basic key operations are:

- "Press and release the key immediately" or "Press the key"
  - = normal key operation during measurement
- "Press and hold the key".






Each key, when pressed or when pressed and held, functions as follows:

Key	When pressed and released	When pressed and held
I/O ON:OFF	Turns the display ON and OFF. The stand is turned off. The weighing mode is enable is available anytime. Pressing the key during and turn the display OFF.	d when the display is turned on. This key
1/10d SAMPLE	In the weighing mode, turns the minimum weighing value ON and OFF. In the counting or percent mode, enters the sample storing mode.	Enters the function table mode. Refer to "10. Function Table".
MODE	No function at the factory setting. Switches the weighing units when units other than "g" are stored in the function setting.	Performs weighing speed adjustment (response adjustment) and self check.
CAL	Performs calibration using the internal mass.	Displays other items of the calibration menu.
© PRINT	Stores the weighing data in memory or outputs to a printer or personal computer depending on the function table settings. (Factory setting = output)	No function at the factory setting.  By changing the function table:  Outputs "Title block" and "End block" for the GLP/GMP compliant report.  Refer to "11-2. GLP Report ".  Displays the data memory menu.
→0/T← RE-ZERO	Sets the display to zero.	· · · · · · · · · · · · · · · · · · ·

# 5. Weighing Units

With the balance, only the unit "g" (gram) was set at the factory.
 The following weighing units and weighing modes are available for selection:



A unit or mode can be selected and stored in the function table as described in the GP series instruction manual "4-2. Changing the Units".

If a weighing mode (or unit of weight) has been turned off, that mode or unit will be missing in the sequence. Tael has four varieties, one of which can be selected and installed at the factory.

For details about the units and modes, see the table below:

Name (unit, mode)	Abbre- viation	Display	Function table (Storing mode)	Conversion factor 1 g =
Gram	g	g	g	1 g
Kilogram	kg	kg	kg	1000 g
Counting mode	pcs	pcs	pcs	
Percent mode	%	%	%	
Ounce (Avoir)	OZ	02	02	28.349523125 g
Troy Ounce	OZt	0Z <del>t</del>	OZ t	31.1034768 g
Metric Carat	ct	ct	ct	0.2 g
Momme	mom	mom	mpm	3.75 g
Pennyweight	dwt	dnt	dnt	1.55517384 g
Grain (UK)	GN	БΝ	БN	0.06479891 g
Tael (HK general, Singapore)				37.7994 g
Tael (HK jewelry)	TL	TL	TL	37.429 g
Tael (Taiwan)	I L			37.5 g
Tael (China)				31.25 g
Tola (India)	t	t	t	11.6638038 g
Messghal	MS	115	M5	4.6875 g
Density mode	DS	Is is used to show the density	<b>I</b> 5	_
Programmable-unit (Multi-unit)	Mlt	_	MLt	

- □ The tables below indicate the weighing capacity and the minimum display for each unit, depending on the balance model.
- When a measurement unit other than gram is used, it is not possible to weigh up to capacity of the balance because the display does not have sufficient digits.
   Use the MC series balance within the values shown in the tables below.

	MC-100KS			
Unit	Capacity	Minimum display		
Gram	101000 g	0.1		
Kilogram	101 kg	0.0001		
Ounce (Avoir)	3562 OZ	0.005		
Troy Ounce	3247 OZt	0.005		
Metric Carat	505000 ct	0.5		
Momme	26933 mom	0.05		
Pennyweight	64945 dwt	0.1		
Grain (UK)	1558668 GN	2		
Tael (HK general, Singapore)	2672 TL	0.005		
Tael (HK jewelry)	2698 TL	0.005		
Tael (Taiwan)	2693 TL	0.005		
Tael (China)	3232 TL	0.005		
Tola (India)	8659 t	0.01		
Messghal	21546 MS	0.05		

# 6. Weighing

# 6-1. Selecting a Weighing Unit (Mode)

Press the MODE key to select a unit or mode for weighing.

The unit "g" (gram) was set at the factory.

To use other units, select and store units and displaying order in the function setting of "Un the". For details on weighing unit storing procedure, refer to the GP series instruction manual, "4-2. Chaning the Units".

# 6-2. Basic Weighing

## 6-2-1. For More Stable Weighing

• To reduce the influence of drafts and vibration, set the following function settings as below.

"Condition ( $\lceil a \land d \rceil$ )" of "Environment, Display ( $\lceil b \land \beta \land f \land c \rceil$ )" to "Slow ( $\rceil$ )"

"Filter (F /L)" of "Environment, Display (685Fnc)" to "Used (/)"

#### **Function Settings**

Refer to "10. Function Table" on page 27 to check or change the function settings.

Class	Item and Parameter		ter	Description
6RSFnc	Cand	Condition	2	Slow response rate, stable value SLOW
Environment Display	F IL	Filter	1	Used

# 6-2-2. When Using as a Mass Comparator

- To avoid eccentric loading errors, place the sample in the center of the weighing pan.
   The weighing pan has markings as a guide to place a weight on the same position every time.
  - Using an AD-8922A remote controller, which is sold separately, the balance can be controlled remotely by the AD-8922A key operations in the same way as when the CAL or RE-ZERO key of the balance is pressed. For the connection procedure between the balance and the AD-8922A, refer to the AD-8922A instruction manual.
- Take measures against causes of weighing error at the installation site, such as changes in temperature, atmospheric pressure, drafts, vibration and static electricity.
   Perform weighing operations in an stable environment.
- The table below lists the weight class and recommended measuring range for the MC-100KS. The measuring range is determined so that the balance repeatability is to be less than one third of the maximum permissible error for each weight class.

Weight class and recommended measuring range

	Model	M C - 1	00KS
	Class	M 1	M 2
	100 kg	<b>†</b>	1
Weight	50 kg		
(Displayed value)	20 kg		
	10 kg		<b>+</b>
		M 1	M 2

## 6-2-3. When Building into a System

- When a special weighing pan is to be designed, the weight of the pan and the material to be weighed should not exceed the weighing capacity of the balance.
   To reduce influences of static electricity and magnetism, use materials other than resin and magnetic material such as iron.
- There is a function available to maintain the previous weight value in non-volatile memory, even if the AC adapter is removed.
   When "Zero upon power-on (P-Łr)" of "Environment, Display (bR5Fnc)" is set to " /", the previous weight value is displayed upon power-on.
   For details, refer to "Zero upon power-on" on page 32.
- There is a function available to perform span calibration only, when performing calibration with a tare on the weighing pan.


  When "Span calibration (5Pn)" of "Environment, Display (ΔΠ5Fnc)" is set to " l", span calibration using the internal mass is performed, with a tare on the weighing pan.

  For details, refer to "Span calibration" on page 32.
- To set a higher response rate (weighing speed) or to batch-weigh small amounts of material, such as a powdery material, refer to "14. Extended Function".

# 7. Weighing Speed Adjustment / Self Check Function

# 7-1. Weighing Speed Adjustment

This function detects the influence on weighing that is caused by drafts and/or vibration at the place where the balance is installed and sets the following three weighing speeds (response characteristics) automatically.



The function has three rates as follows:

Changing the weighing speed changes the display refresh rate.

Indicator	Parameter	Weighing Speed Stability		Display refresh rate
FAST	Cond 0	Fast response,	Sensitive value	If the weighing speed is changed as follows:
MID.	Cond I	1	I.	MID. or SLOW FAST =10 times/second
SLOW	Cond 2	Slow response,	Stable value	FAST MID. or SLOW = 5 times/second

- Step 1 Press and hold the MODE key until RESPONSE is displayed. And then, press the MODE key again quickly.
- Step 2 Press the MODE key to select a weighing speed. Either FAST, MID. or SLOW can be selected.
- Release
  Press again
  MODE

  Release
  Press again
  MODE

  Select a parameter by pressing the key.

  Release and wait

End

0.0 a

Press and hold

Step 3 After a few seconds of inactivity the balance displays End.

Then, it returns to the weighing mode and displays the updated response indicator. The response indicator remains displayed for a while.

#### **Note**

- The weighing speed adjustment can be changed at "Condition ([lond)" of "Environment, Display (bR5Fnc)" in the function table. Refer to "10. Function Table" for details.
- □ To set a refresh rate of 5 times/second when the response rate is FAST or 10 times/second when the response rate is MID. or SLOW, change the "Display refresh rate (5Pd)" parameter of "Environment, Display (bfl5Fnc)" in the function table.
- If the weight value is not stabilized due to drafts or vibration when "[and []" is selected by the automatic response adjustment, change the parameter of "[and" manually in the function table.

# 7–2. Self Check Function with Response Adjustment

This function automatically updates the response adjustment by analyzing the influence of the environment on the weighing data and also self-checks the balance performance using the internal mass.

Press and hold

MODE

ΟX

[].[] g

Release

Result

[ X

[ H

- Step 1 Press and hold the MODE key until RESPONSE is displayed, and then release the key.
- Step 2 The balance automatically starts to check the balance performance and sets the response characteristic.

# Caution Do not allow vibration or drafts to affect the balance during adjustment.

Step 3 After automatic adjustment, the balance displays the updated response indicator and returns to the weighing mode.

The response indicator remains displayed for a while.

#### Example of display

MID. and OK: The example of display indicates that the result of the self check is good and MID. is selected as the response rate.

#### **Note**

- If improper performance is found in the self check, the balance displays [[H no]].
   Contact the local A&D dealer for repair.
- If the automatic response adjustment fails, the balance displays [H nb]. Check the ambient conditions such as breeze and vibration, also check the weighing pan. Then, perform the adjustment again. To return to the weighing mode, press the CAL key.

# 8. Calibration

# 8-1. Calibration Group

The balance has the following modes as a calibration group.

#### **Calibration**

Automatic self calibration (Calibration due to changes in temperature)

Calibration using the internal mass (One-touch calibration)

Calibration using an external weight

#### **Calibration Test**

Calibration test using an external weight (Calibration test does not perform calibration)

#### Correction of the internal mass value

#### **Terms**

The following terms are defined as follows:

Internal mass = Built-in calibration weight

External weight = A weight that you have. Referred to as a calibration weight when

used for calibration.

Calibration weight = A weight used for calibration

Target weight = An external weight used for calibration test

#### Caution

Calibration adjusts the balance for accurate weighing.

Besides periodic calibration and before each use, perform calibration when:

- The balance is installed for the first time.
- The balance has been moved.
- The ambient environment has changed.
- Do not allow vibration or drafts to affect the balance during calibration.
- □ To output the GLP/GMP compliant report using the RS-232C interface, set "GLP output ( ι¬F¬)" of "Data output (d¬¬¬¬)". Refer to "10. Function Table". Time and date can be added to the GLP report. If the time or date is not correct, adjust them. Refer to the GP series instruction manual "9-9. Clock and Calendar Function".
- □ Calibration test is available only when "GLP output ( nnFa)" of "Data output (daut)" is set to " l" or "2",
- □ The calibration and calibration test data can be stored in memory. To store them, set "Data memory (d用t用)" to "∃". Refer to the GP series instruction manual "11. DATA MEMORY" for details.

#### Caution on using an external weight

- The accuracy of an external weight can influence the accuracy of weighing.
- Select an appropriate weight for calibration and calibration test from the following table.

Model	Usable calibration weight	Adjustable range
MC-100KS	60 kg, 80 kg, <b>100 kg</b>	-15.0 g ~ +15.9 g

The calibration weight in **bold type**: factory setting

The calibration weight value can be adjusted within the range above.

Display	
•	This indicator means "In process of measuring calibration data".
	Do not allow vibration or drafts to affect the balance while the indicator is displayed.

# 8-2. Automatic Self Calibration

#### Automatic self calibration due to changes in temperature

This function automatically calibrates the balance when the balance detects an ambient temperature change. If GLP output is selected in the function table, the balance outputs the calibration report or stores the data in memory. Automatic self calibration functions even if the display is turned off (standby state). Refer to "9-1. Permit or Inhibit" for the operation.

If something is on the weighing pan, the balance judges that it is in use and does not

#### Caution

•	ic self calibration. To maintain the calibrated state, keep the ar while not in use.
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Indicates that the balance detects a change in ambient temperature and automatic self calibration will start. If the balance is not used for a few minutes with this indicator blinking, the balance performs automatic self calibration. The blinking duration depends on the environment.
•	Indicates that the balance is measuring calibration data. Do not allow

**Note** The balance can be used while the indicator blinks. But, it is recommended that to maintain the accuracy, stop using the balance and confirm that there is nothing on the pan and allow the balance to perform self calibration.

vibration or drafts to affect the balance while this indicator is displayed. After calibration, the balance returns to indicate the previous display.

## 8-3. One-Touch Calibration

#### Calibration using the internal mass

This function calibrates the balance using the internal mass. The only operation required is to press the CAL key.

- Step 1 Connect the AC adapter and warm up the balance for at least 30 minutes with nothing on the weighing pan.
- Step 2 Press the CAL key.
- Step 3 The balance displays [[RL In]] and performs calibration using the internal mass. Do not allow vibration or drafts to affect the balance.
- Step 4 The balance displays <code>[End]</code> after calibration. If the "GLP output (<code>InFa</code>)" parameter of the function table is set to "!" or "2", the balance displays <code>[GLP]</code> and outputs the "calibration report" using the RS-232C interface or stores the data in memory. Refer to "11-2. GLP Report" and "Data memory (dRtR)" of the function table for details.
- Step 5 The balance will automatically return to the weighing mode after calibration.

#### About the internal mass

The value of the internal mass may change due to aging, corrosion or other damage caused by the operating environment. Check the internal mass periodically. Correct the internal mass value as necessary. Refer to "8-6. Correcting the Internal Mass Value".

To maintain the weighing accuracy, perform the calibration using an external weight periodically, as described below.

# 8-4. Calibration Using an External Weight

This function calibrates the balance using an external weight.

Step 1 Connect the AC adapter and warm up the balance for at least 30 minutes with nothing on the weighing pan.

Step 2 Press and hold the CAL key until [FRLout] is displayed, then release the key.

Step 3 The balance displays [FRL II].

 If you want to change the calibration weight, press the SAMPLE key and go to step 4.

 If you use the calibration weight value stored in the balance, go to step 5.

Step 4 Specify the calibration weight value as follows:

SAMPLE key... To switch between the calibration weight selection mode (All of the digits blinking) or the value adjustment mode (The selected digits blinking).

The digits up to the 1<sup>st</sup> decimal place can be adjusted.


RE-ZERO key. To select the calibration weight (All of the digits blinking) or adjust the value (The selected digits blinking). Refer to page 18.

PRINT key ······ To store the new weight value. Even if the AC adapter is removed, the data is maintained in non-volatile memory.

CAL key ...... To cancel the operation and return to [FIL []].

Step 5 Confirm that there is nothing on the pan and press the PRINT key. The balance measures the zero point. Do not allow vibration or drafts to affect the balance. The balance displays the calibration weight value.

- Step 6 Place the displayed calibration weight on the pan and press the PRINT key. The balance measures the calibration weight. Do not allow vibration or drafts to affect the balance.
- Step 7 The balance displays *End*. Remove the weight from the pan.
- Step 9 The balance will automatically return to the weighing mode.
- Step 10 Place the calibration weight on the pan and confirm that the value displayed is within ±20 digits of the specified value. If it is not within the range, check the ambient conditions such as breeze and vibration, also check the weighing pan. Then, repeat steps 1 to 10.



# 8-5. Calibration Test Using an External Weight

This function tests the weighing accuracy using an external weight and outputs the result. This is available only when the "GLP output ( mFa)" parameter is set to " /" or "2". (Calibration test does not perform calibration)

- Step 1 Connect the AC adapter and warm up the balance for at least 30 minutes with nothing on the weighing pan.
- Step 2 Press and hold the CAL key until [[[aut] is displayed, then release the key.
- Step 3 The balance displays [[[ ]].
  - If you want to change the target weight, press the SAMPLE key and go to step 4.
     A list of usable weights is shown on page 19.
  - If you use the target weight value stored in the balance, go to step 5.
- Step 4 Specify the target weight value as follows:

SAMPLE key... To switch between the target weight selection mode (All of the digits blinking) or the value adjustment mode (The selected digits blinking).

The digits up to the 1<sup>st</sup> decimal place can be


The digits up to the 1<sup>st</sup> decimal place can be adjusted.

RE-ZERO key. To select the target weight (All of the digits blinking) or adjust the value (The selected digits blinking). Refer to page 18.

PRINT key ······ To store the new weight value. Even if the AC adapter is removed, the data is maintained in non-volatile memory.

CAL key ...... To cancel the operation and return to [[[ []].

- Step 5 Confirm that there is nothing on the pan and press the PRINT key. The balance measures the zero point and displays the measured value. Do not allow vibration or drafts to affect the balance. The balance displays the target weight value.
- Step 6 Place the displayed target weight on the pan and press the PRINT key. The balance measures the target weight and displays the measured value. Do not allow vibration or drafts to affect the balance.
- Step 7 The balance displays *End*. Remove the weight from the pan.
- Step 8 The balance displays LLP and outputs the "calibration test report" using the RS-232C interface or stores the calibration test data in memory. Refer to "11-2. GLP Report" of the function table for details.
- Step 9 The balance will automatically return to the weighing mode.




# 8-6. Correcting the Internal Mass Value

The balance can correct the internal mass value within the range shown below. This function corrects the internal mass value to conform to an external weight. The corrected mass value is maintained in non-volatile memory even if the AC adapter is removed. The internal mass value is corrected as follows:

 Model
 Target
 Range

 MC-100KS
 100 kg
 ±50.0 g



- Step 1 Calibrate the balance using the internal mass. (one-touch calibration).

  Place the external weight and find out the correction value.

  Example for correcting the weight value by +3.0 g in 100 kg:

  If correcting the weight value by +3.0 g in 50 kg, the correction value is +6.0 g as the target value is 100 kg.
- Step 2 Press the ON:OFF key to turn off the display.
- Step 3 While pressing and holding the PRINT key and the SAMPLE key, press the ON:OFF key. The balance displays P5.
- Step 4 Press the PRINT key. Then the balance displays the function switches. Set the function table switch and internal mass correction switch to " /" as shown above using the following keys.

  SAMPLE key···To select the switch to change the value.

  The selected digit blinks.

RE-ZERO key .. To change the parameter of the switch selected.

Function table switch


Correction switch of internal mass

- Step 5 Press the PRINT key to store the new setting. The balance returns to the weighing mode.
- Step 6 Press and hold the SAMPLE key to enter the function table and release the key when basen is displayed.
- Step 7 Press the SAMPLE key several times until [5 in] is displayed, then release the key.
- Step 8 Press the PRINT key to enter the procedure for correcting the internal mass value.
- Step 9 Correct the internal mass value using the following keys.

  RE-ZERO key. To select the value. (-500 digits appear after +500 digits)

PRINT key.....To store the new value and display the next menu item of the function table.

CAL key .....To cancel the correction and display the next menu item of the function table.



1/10d SAMPLE

P 5

PRINT

held down


With these keys

I/O

ON:OFF

Press the key

Step 10 Press the CAL key to return the weighing mode.



- Step 11 Press the CAL key to calibrate the balance using the internal mass.
- Step 12 Place the external weight on the pan and confirm that the correction has been performed properly. In this example, confirm that the value displayed is within the range that is described at "Accuracy after calibration using the internal mass" of "17. Specifications". If the value is incorrect, repeat the correction.

# 9. Function Switch And Initialization

#### 9–1. Permit or Inhibit

The balance stores parameters that must not be changed unintentionally (Example: Calibration data for accurate weighing, Data for adapting to the operating environment, Control data for the RS-232C interface). There are five switches for the purpose of protecting parameters. Each switch can select either "permit" or "inhibit". The "inhibit" protects parameters against unintentional operations.

- Step 1 Press the ON:OFF key to turn off the display.
- Step 2 While pressing and holding the PRINT key and the SAMPLE key, press the ON:OFF key to display P5.
- Step 3 Press the PRINT key. Then the balance displays the function switches.
- Step 4 Set the switches using the following keys.

SAMPLE key To select a switch to change the parameter. The selected switch blinks.


RE-ZERO key To change the parameter of the switch selected.

To inhibit changes. (Can not be used.)

To permit changes. (Can be used.)

PRINT key To store the new parameter and return to the weighing mode.

CAL key To cancel the operation and return to the weighing mode.



To permit correction

# 9-2. Initializing the Balance

This function returns the following parameters to factory settings.


- Calibration data
- Function table
- The sample unit mass value (counting mode),
   100% reference mass value (percent mode)
- The data that is stored in the balance using the data memory function
- External calibration weight and target weight value
- Function switch settings

#### Note Be sure to calibrate the balance after initialization.

- Step 1 Press the ON:OFF key to turn off the display.
- Step 2 While pressing and holding the PRINT key and the SAMPLE key, press the ON:OFF key to display 75.
- Step 3 Press the SAMPLE key to display [[Lr].
- Step 4 Press the PRINT key.

  To cancel this operation, press the CAL key.
- Step 5 Press the RE-ZERO key to display [Lr [io]
- Step 6 Press the PRINT key to initialize the balance.

  The balance will automatically return to the weighing mode.



# 10. Function Table


This function table reads or rewrites the parameters that are stored in the balance. These parameters are maintained in non-volatile memory, even if the AC adapter is removed.

## 10-1. Sequence of the Function Table

This function table menu consists of two layers. The first layer is the "Class" and the second layer is the "Item". Each item stores a parameter. New parameters are applied to the balance after the PRINT key is pressed.

#### **Example**

This example sets "Stores weighing data" for "Data memory" and "1 minute" for "Interval time".



Check the settings and condition before changing parameters.

# 10-2. Display and Operation Keys

0	The symbol "O" indicates that the parameter displayed is in effect.					
1/10d SAMPLE	When pressed and held in the weighing mode, enters the function table mode. Selects the class or item in the function table mode.					
→0/T← RE-ZERO	Changes the parameter.					
© PRINT	When a class is displayed, moves to an item in the class.  When an item is displayed, stores the new parameter and displays the next class.					
CAL	When an item is displayed, cancels the new parameter and displays the next class.  When a class is displayed, exits the function table mode and returns to the weighing mode.					

# 10-3. Details of the Function Table

Class	Item and Parame	ter	Desc	ription
bЯ5Fпс Environment Display	Eand Condition	0 • 1 2	Fast response, sensitive value MID.  Slow response, stable value SLOW	Can be changed by response adjustment. With "Hold I", sets the averaging time.
	Stability band width	• I	Stable when within ±1 digit  Stable when within ±3 digits	The stabilization indicator illuminates with the display fluctuation within the range. With "Hald I", sets the stable range.
	HoLd Hold function	<b>-</b> []	OFF ON	Holds the display when stable in animal mode. With "Hold I", ANIMAL turns on.
	לרכ Zero tracking	- I - I	OFF Normal Strong Very strong	Keeps zero display by tracking zero drift.
	5Pd Display refresh rate	• O	Approx. 5 times/second Approx. 10 times/second	Period to refresh the display
	Pnt Decimal point	<b>-</b> []	Point (.) Comma (,)	Decimal point format
	P-on Auto display-ON	• [] 	OFF ON	Turns on the weighing mode display when the AC adapter is connected.
	Poff Auto display-OFF	<b>•</b> []	OFF ON (10 minutes)	Turns off the display after 10 minutes of inactivity.
	ଘ୍ର ମ Capacity indicator	<b>-</b> 0	OFF ON	Capacity indicator.  Zero: 0%  Maximum capacity: 100%
	Rdd Accumulation function	<b>-</b> 0	OFF ON	Displays and outputs the total value of the weighing data.
	ากน์ Display at start	<b>-</b> 0	Does not display Displays	Select whether or not to display the smallest displayable weighing value at weighing start.
	F IL Filter	<b>-</b> 0	Not used Used (when the balance is used a	
	P-E- Zero upon power-on	• O !	Sets the display to zero.  Does not set the display to zero.	Displays the previous value. e-zero operations frequently.
	5Pn Span calibration	<b>-</b> 0	Performs zero and span calibration  Performs span calibration only.  Span calibration using the internal mass is possible with a tare on the weighing pan. Refer to "Span calibration" on page 31.	
EL Rau Clock	Refer to the GP manua	ıl "9-9. (	Clock and Calendar Function"	Confirms and sets the time and date. The time and date are added to the output data.
EP Fnc Comparator	CP Comparator mode 3		No comparison  Comparison, excluding "near zero" when stable value or overloaded	
			Comparison, including "near zero" when stable value or overloaded Continuous comparison, excluding "near zero" Continuous comparison, including "near zero"	
	[P ,n Data input method	<b>-</b> 0	Set the upper lower limit value Set the reference value	Select [P H   or [P La. Select [P r EF or [P Lāt.
	[P-r Comparison results	<b>-</b> 0	Not added Added	Select whether or not to add the comparison results to the output data.

<sup>• :</sup> Factory settings. Digit is a unit of minimum weighing value.

Class	Item and Parameter		Description	
[P Fnc	[P-b	<b>-</b> []	OFF	Displays the results on the main
Comparator	Main display comparison	1	ON	portion of the display in place of the weight value.
Displayed	6EP_	<b>-</b> []	OFF	Select whether or not to sound the
only when	LO buzzer	1	ON	LO buzzer.
Comparator output	bEP-	<b>-</b> []	OFF	Select whether or not to sound the
(GP-04) is	OK buzzer	- 1	ON	OK buzzer.
installed	PED-	<b>-</b> []	OFF	Select whether or not to sound the
(	HI buzzer	1	ON	HI buzzer.
[P H   Upper limit			Refer to the GP manual	Displayed when [ P in []
EP Lo			"9-10. Comparator Function"	is selected.
Lower limit			parametri anticon	
[P rEF				
Reference va	lue		Refer to the GP manual	Displayed when [P in
[P Lnt			"9-10. Comparator Function"	is selected.
Tolerance				Accepte the DDINT key only when
		<b>-</b> []	Key mode	Accepts the PRINT key only when the display is stable.
		,	Auto print mode A	
	Prt	i	(Reference = zero)	Outputs data when the display is stable and conditions of RP-P, RP-b
	Data output mode	2	Auto print mode B	and the reference value are met.
			(Reference = last stable value)	
		3	Stream mode / Interval memory mode	With dRER 0, outputs data at the specified display refresh rate; with dRER 2, uses interval memory.
	위우-유 Auto print polarity	<b>-</b> []	Plus only	Displayed value>Reference
		1	Minus only	Displayed value <reference< td=""></reference<>
		2	Both	Regardless of displayed value
	   ЯР-Ь	<b>-</b> []	10 digits	Difference between reference value and displayed value
	Auto print difference	1	100 digits	
		2	1000 digits	
dout	ਰਸ਼ੁਸ਼ Data memory	<b>-</b> []	Not used	
Data output		1	Stores unit mass in counting mode	
		2	Stores weighing data	Related items:
		3	Stores calibration data	Prt, int, d-no, 5-td, inFo
		4	Stores comparator settings	
		5	Stores tare value	
		<b>-</b> []	Every display refresh	
	וחל Interval time	!	2 cocondo	
		'		
			5 seconds	
		3	10 seconds	Interval time in the interval memory
		<u> </u>	30 seconds	mode when using Prt 3, dRtR 2
		5	1 minute	
		Б	2 minute	
		7	5 minute	
		8	10 minute	

<sup>• :</sup> Factory settings. Digit is a unit of minimum weighing value.

Class	Item and Parame	ter	Desc	ription
	d-no	<b>-</b> []	No output	Refer to the GP manual "11. DATA
	Data number output	1	Output	MEMORY"
		<b>-</b> []	No output	Calagta subathar or not the time or
	5-Ed		Time only	Selects whether or not the time or date is added to the weighing data.
	Time/Date output	2	Date only	Refer to the GP manual "9-9. Clock and Calendar Function" for details.
		3	Time and date	
	5- ıd	<b>-</b> []	No output	Selects whether or not the ID
	ID number output	1	Output	number is output.
dout	PUSE	<b>-</b> []	No pause	Selects the data output interval.
Data output	Data output pause	1	Pause (1.6 seconds)	Gelecis the data output interval.
	RL-F	<b>-</b> []	Not used	Selects whether or not automatic
	Auto feed	1	Used	feed is performed.
	ınFa	<b>-</b> []	No output	Selects the output format for the GLP/GMP compliant report.
	· · · <del>-</del>		AD-8121 format	For how to set time and date to be
	GLP output	2	General data format	added, refer to the GP manual "9-9. Clock and Calendar Function".
	Ar-d	<b>-</b> []	Not used	Adjusts zero automatically after data
	Zero after output	1	Used	is output
	-	0	600 bps	
	ЪР5 Baud rate	1	1200 bps	
		• Z	2400 bps	
		3	4800 bps	
		4	9600 bps	
	ЬЕРг	<b>-</b> []	7 bits, even	
		1	7 bits, odd	
	Data bit, parity bit	2	8 bits, none	
	[rLF	<b>-</b> []	CR LF	CR: ASCII code 0Dh
5 ,F	Terminator	1	CR	LF: ASCII code 0Ah
Serial		<b>-</b> []	A&D standard format	
interface		1	DP format	
interiace	E YPE	2	KF format	Refer to "10-6. Description of the
	Data format	3	MT format	Item "Data Format"".
		4	NU format	
		5	CSV format	
	E-UP	0	No limit	Selects the wait time to receive a
	Timeout	<b>-</b> /	1 second	command.
	Er[d	<b>-</b> []	No output	AK: ASCII code 06h
	AK, Error code		Output	
	[ <del> </del>	<b>-</b> []	Not used	Controls CTS and RTS.
	CTS, RTS control	- 1	Used	
d5 Fnc Density	Ldın	<b>-</b> []	Water temperature	Available only when density mode (☐G) is selected. Refer to the GP manual "13. DENSITY
function	Liquid density input	1	Liquid density	MEASUREMENT."

<sup>• :</sup> Factory settings. Digit is a unit of minimum weighing value.

Class	Item and Parame	ter	Description	
ñLE			Available only when programmable-unit mode is selected.	
Programmable-unit (Multi-unit)			Refer to the GP manual "12. PROGRAMMABLE-UNIT" for details.	
Un it			Refer to "5. Weighing Units".	
Unit				
[5 in			Displayed only when the internal mass value correction switch is set	
Internal mass	correction		to /. Refer to "8. Calibration".	
ا اط ا			Refer to "11. ID Number And GLP Report".	
ID number se	tting	П	'	
	F I-b Averaging range for the first moving average	- 1 - 3 - 4 - 5	Small  Large	
ErFnc Extended function	F 1-E Averaging time for the first moving average	3 4 5	No averaging 0.5 second 1.0 second 1.5 seconds 2.0 seconds 2.5 seconds 3.2 seconds	
Displayed only when "Filter (F IL)" is set to ""	F2-b Averaging range for the second moving average	0 - 1 - 2 - 3 - 4 - 5	Small  Large	
	F2-Ł Averaging time for the second moving average	3 4 • 5	No averaging  0.5 second  1.0 second  1.5 seconds  2.0 seconds  2.5 seconds  3.2 seconds	

<sup>• :</sup> Factory settings. Digit is a unit of minimum weighing value.

#### Caution

The balance may not transmit the data completely at the specified refresh rate, depending on the baud rate or data added to the weighing data such as time, date and ID number.

# 10-4. Description of the Class "Environment, Display"

#### Condition (Land)

Land [] This parameter is for sensitive response to the fluctuation of a weight value. Used

for powder target weighing, weighing a very light sample or when quick response weighing is required. After setting, the balance displays FAST.

This parameter is for stable weighing with slow response. Used to prevent a weight value from drifting due to vibration or drafts. After setting, the balance displays SLOW.

Notes In automatic response adjustment, the weighing speed is selected automatically.

With "Hold function (Hald)" set to "ON (I)", this item is used to set the averaging time.

#### Stability band width (5L-b)

This item controls the width to regard a weight value as a stable value. When the fluctuation per second is less than the parameter, the balance displays the stabilization indicator and outputs or stores the data. The parameter influences the "Auto print mode"

This parameter is used for sensitive response of the stabilization indicator. Used for exact weighing.

5½-b 2 This parameter ignores slight fluctuation of a weight value. Used to prevent a weight value from drifting due to vibration or drafts.

Note With "Hold function (Hold)" set to "ON ( l)", this item is used to set the stabilization range.

## Zero upon power-on (P-Łr)

When a hopper is attached to the weighing pan and loss-in weighing is performed, the remaining amount of the material will become unknown if tare is performed each time a weighing starts.

When "p-tr" is set to " l", tare is not performed at weighing start. So, the remaining amount of the material can be monitored, when the power is turned on again after it was turned off.

## Span calibration ( $5P_{\cap}$ )

When a hopper is attached to the weighing pan and calibration is to be performed with the hopper attached, set "5Pn" to "l". When the tare value (hopper and other devices attached) is within the value in the table below, calibration using the internal mass is possible.

Model	Tare value
MC-100KS	99 kg or less

# 10-5. Description of the Item "Data Output Mode"

The parameter setting of "Data output mode (Pr L)" applies to the performance when the "Data memory (dRLR)" parameter is set to "Z" (to store the weighing data) and when the data is transmitted using the RS-232C interface.

#### Key mode

When the PRINT key is pressed with the stabilization indictor turned on, the balance outputs or stores the weighing data and the display blinks one time.

Required setting doub Prt [] Key mode

#### Auto print modes A and B

When the displayed value is stable and the conditions of "Auto print polarity", "Auto print difference" and reference value are met, the balance outputs or stores the weighing data.

When the PRINT key is pressed with the stabilization indictor turned on, the balance outputs or stores the data and the display blinks one time.

#### Auto print modes A

Example For weighing each time a sample is added (or removed), with

"#r - d" set to " /" (to adjust zero after the data is output)."

Required setting doub Prt / Auto print mode A (reference = zero)

dauLRP-PAuto print polaritydauLRP-bAuto print differencedauLRr-dIZero after output

#### Auto print modes B

Example For weighing while a sample is added.

Required setting doub Prt 2 Auto print mode B (reference = last stable value)

לפטב אף-ף Auto print polarity לפטב אף-ם Auto print difference

#### Stream mode

The balance outputs the weighing data at the specified display refresh rate, regardless of the display condition. The display does not blink in this mode. The interval memory mode is used when the "Data memory (dRLR)" parameter is set to "2" (to store the weighing data).

Example For monitoring data on the AD-8922A remote display.

Required setting doub Prb 3 Stream mode

dout dRtR 0 Data memory function is not used

bRSFnc 5Pd Display refresh rate

5 F 6P5 Baud rate

Caution The balance may not transmit the data completely at the specified refresh rate, depending on the baud rate or data added to the weighing data such as time, date and ID number.

#### Interval memory mode

The weighing data is periodically stored in memory.

Example For periodical weighing without a personal computer command and

to output all of the data, to a computer, at one time.

Time and date can be added with "Time/Date output (5 - ½ d)".

Required setting doub Prb 3 Interval memory mode

dout dRtR ≥ Data memory function is used

doub interval time

Optional setting doub 5-bd/, 2, or 3 Adds the time and date.


# 10-6. Description of the Item "Data Format"

#### A&D standard format 5 if LYPE 0

This format is used when the peripheral equipment can receive the A&D format.

If an AD-8121B is used, set the printer to MODE 1 or 2.


- □ This format consists of fifteen characters excluding the terminator.
- □ A header of two characters indicates the balance condition.
- □ The polarity sign is placed before the data with the leading zeros. If the data is zero, the plus sign is applied.
- The unit, consisting of three characters, follows the data.



# DP (Dump print) format 5 F EYPE 1

This format is suitable for the peripheral equipment that prints the received data as is. If an AD-8121B is used, set the printer to MODE 3.

- □ This format consists of sixteen characters excluding the terminator.
- A header of two characters indicates the balance condition. No overload header is used.
- The polarity sign is placed before the data, with spaces in place of leading zeros, if the data is not zero or overloaded.
- The unit, consisting of three characters, follows the data.




### KF format

### SIF HYPF 2

This is the Karl-Fischer moisture meter format and is used when the peripheral equipment can only communicate using this format.

- □ This format consists of fourteen characters excluding the terminator.
- This format has no header characters.
- □ The polarity sign is placed before the data, with spaces in place of leading zeros, if the data is not zero or overloaded.
- This format outputs the unit only for a stable value.




### MT format

### 5 if LYPE 3

This format is used when the peripheral equipment of other manufacturer is connected. Please note that the connection is not guaranteed.


- A header of two characters indicates the balance condition.
- The polarity sign is used only for negative data.
- The weighing data uses spaces in place of the leading zeros.
- The character length of this format changes dependent upon the unit



### NU (numerical) format 5 iF EYPE 4

This format outputs only numerical data.

- This format consists of nine characters excluding the terminator.
- □ The polarity sign is placed before the data with the leading zeros. If the data is zero, the plus sign is used.



### **CSV** format

### S IF LYPE S

- □ This format separates the data of A&D standard format and the unit by a comma (, ).
- This format outputs the unit even when the data is overloaded.
- □ When the ID number, data number, time and date are added at "Data output (dout)" of the function table, outputs ID number, data number, date, time and weighing data in this order and separates each item by a comma and treats all the items as one group of data.

LAB-123, No,012, 2012/12/31,							_	12:	34:	56,	<u> </u>	ST,+	100	000	0.0, ∟ ∟g <cr><lf></lf></cr>			
ID number Data number Date							Time				Weighing data							
S	Т	,	+	1	0	0	0	0	0		0	,	ш	ш	g	$C_R$	LF	
О	L	,	+	9	9	9	9	9	9	9	Ε	+	1	9	,			g C <sub>R</sub> L <sub>F</sub>

## 10-6-1. Description of the Data Format Added to the Weighing Data

**ID** number

dout 5-id 1

The number to identify a specific balance.

□ This format consists of seven characters excluding the terminator.

Data number

dout d-no 1

This format outputs the data number just before the data is transmitted using the RS-232C interface.

- □ This format consists of six characters excluding the terminator.
- □ When CSV format (5 ,F Ł ڬPE 5) is selected, the period ( . ) is replaced with a comma ( , ).

Data number Terminator

Date

dout 5-td 2 or 3

□ The date output order can be changed in "Clock ([L 위dd)".

The year is output in a four-digit format.

Time

dout 5-td 1 or 3

□ This format outputs time in 24-hour format.

### Tare value


When the tare value in memory is recalled, the tare value is output before the weighing data.

Р	Т	,	+	0	0	0	1	2	3	4	₋ g	CRLF	Tare value recalled from memory
N		,	+	0	0	0	5	6	7	8	_ g	CRLF	Net value

### **Comparison results**

By setting "Comparison results ([P-r])" of the function table to " l", the comparison results can be added to the data output using the RS-232C serial interface. Use A&D standard format ( $L \ PE \ \square$ ).

The comparison results are added after the header in A&D standard format as below.



#### **Note**

When the data described above is added to the weighing data, the output is in the following order: ID number, Data number, Date, Time and Weighing data.

## 10-7. Data Format Examples

																			_
Stable	A&D	S	Т	,	+	0	0	0	0	1	2		7	ப	ப	g	$c_R$	LЕ	
	DP	W	Т	ш	ш	ш	ш		ш	+	1	2		7	ш		g	$C_{R}$	₹LF
• 12.7 g	KF	+						1	2		7	ш	g	ш	ш	$C_{R}$	L <sub>F</sub>		
/L. / g	ΜT	S		ш	ш	ш		J		1	2		7	ш	g	$C_{R}$	LF		
	NU	+	0	0	0	0	1	2		7	$C_{R}$	LF							
																			7
Unstable	A&D	U	S	,	_	0	0	1	8	3	6		9	ш	ш	g	$c_R$	LF	
	DP	U	S		ш	ш	ш	-	1	8	3	6		9	ப	ப	g	$c_R$	₹ LF
- 1836.9 g	KF	_	ш	ш	ш	1	8	3	6		9		ш	ш	ப	$c_R$	LF		
[ g L.U.U.g	ΜT	S	D	ш	ш	ш	-	1	8	3	6		9		g		LЕ		
	NU	-	0	0	1	8	3	6		9	$c_R$	LF							
Overload		_		I															٦
Positive error	A&D	0	L	,	+	9	9	9	9	9	9	9	E	+	1	9	CR	۱	
FUSILIVE ETIOI	DP	ш	ш	ш	ш	ш	ш	ш	ш		ш	ш	ш	ш	ш	ш	ш	CR	L <sub>F</sub>
E g	KF	ш	ш	ш	ш	ш	ш	Н	ш	ш	ш	ш	ш	ш	ш	CR	LF		
_ 9	ΜT	S	ı	+		LЕ							1						
	NU	+	9	9	9	9	9	9	9	9	$C_{R}$	LF							
Overload	4 0 D			1	1				_				_	Ι.	1 4				٦
Negative error	A&D	0	L	,	-	9	9	9	9	9	9	9	E	+	1	9	<sup>∪</sup> R	냑	
Trogative error	DP	ш	ш	ш	ш	$\Box$		<u></u>	-	Е				ш	ш			<sup>∪</sup> R	\L <sub>F</sub>
- E g	KF		<u></u>	ш			ш	L	ш	ш	ш	ш	ш	ш	ш	$c_R$	L <sub>F</sub>		
	MT	S		-	CR	LF	_	_		_			1						
	NU	_	9	9	9	9	9	9	9	9	$C_R$	LF							
Unit			Д	&D	)			D.P.				KF					M	Г	

Unit		A&D	D.P.	KF	MT
g	g	g	g	g	<u>ப</u> g
kg	kg	∟ k g	ഥ k g	니 k g 니	니 k g
Counting mode	pcs	⊔ P C	⊔ P C	□ p c s	⊔ P C S
Precent mode	%	니니%	<u> </u>	山%山口	<b>山</b> %
Ounce (Avoir)	$\Box Z$	⊔ O Z	⊔ O Z		_ 0 Z
Troy Ounce	□	o z t	o z t	ப o z t	⊔ o z t
Metric Carat	⊏ t	∟ c t	_ c t	∟ c t ∟	∟ c t
Momme	m 🗆 m	m o m	m o m	⊔ m o m	⊔ m o
Pennyweight	dnt	d w t	d w t	∟ d w t	d w t
Tael (HK general, Singapore)	T <u>L</u>	∟ t I	ப t I	ப t I s	ш t I
Tael (HK, jewelry)	ΓL	山 t I	_ t I	山 t l h	
Tael (Taiwan)	T <u>L</u>	⊔ t I	山 t I	」 t I t	
Tael (China)	ΓL	山 t I	山 t l	⊔ t I c	⊔ t I
Tola (India)	t	ப ப t	<u>ப</u> ப t	∟ t O I	山 t
Messghal	M5	m e s	m e s	⊔MS⊔	□ m
Density	115	∟ D S	⊔ D S	L D S L	□ D S
Multi	(Blank)				

 <sup>□</sup> Space, ASCII 20h
 □ Carriage Return, ASCII 0Dh
 □ Line Feed, ASCII 0Ah

## 11. ID Number And GLP Report

- The ID number is used to identify the balance when Good Laboratory Practice (GLP) or Good Manufacturing Practice (GMP) is used.
- □ The ID number is maintained in non-volatile memory even if the AC adapter is removed.
- □ The output format for the GLP/GMP compliant report is selected at "GLP output ( ¬¬F¬)" of the function table and can be output to a personal computer or printer using the RS-232C serial interface.
- The GLP/GMP compliant report includes the balance manufacturer, model, serial number, ID number, date, time and space for signature for the weighing data, and the weight used and results for calibration or calibration test data.
- The balance can output the following for the GLP/GMP compliant report.
  - "Calibration report" of the calibration, using the internal mass (Calibration due to changes in temperature and one-touch calibration.)
  - "Calibration report" of the calibration, using an external weight.
  - "Calibration test report" of the calibration test, using an external weight.
  - "Title block" and "End block" for the weighing data.
- Calibration and calibration test data can be stored in memory to output several reports at the same time. Refer to the GP series instruction manual "11. DATA MEMORY" for details.
- For details on confirming and setting the time and date, refer to the GP series instruction manual "9-9. Clock and Calendar Function".

### Setting the ID Number Step 1 Press and hold the SAMPLE key until bR5Fnc of the function table is displayed, then release the key. Step 2 Press the SAMPLE key several times to display 3 Press the PRINT key. Set the ID number using the following keys. Step RE-ZERO key......To set the character of the digit selected. Refer to the display character set shown below. SAMPLE key, MODE key ...... To select the digit to change the value. CAL key......To cancel the new ID number and display basence 4 With b85Fnc displayed, press the CAL key to return to the weighing mode. Step Display character set 0 1 2 3 4 5 6 7 8 9 A|B|C|D|E|F|G|H|I|J|K|L|M|N|O|P|Q|R|S|T|U|V|W|X|R b E d E F G H 123456789 1212 |ñ|n|<u>o</u>|P|9|r \_ Space

## 11-2. GLP Report


Set the following parameters to output the GLP/GMP compliant report.

- To print the report, set the "GLP output (nFa)" parameter to " /" and use MODE 3 of the AD-8121B. Refer to "12-2-1. Connection to the AD-8121B Printer" for details on using the printer.
- To output the report to a personal computer using the RS-232C interface, set the "GLP output ( ¬¬F¬□)" parameter to "¬□".
- □ If the time and date are not correct, set the correct time and date in "Clock ([L Rdd])" of the function table.

#### **Notes**

□ For operational details about calibration and calibration test, refer to "8. Calibration".

### Calibration report using the internal mass



□ Space, ASCII 20h

Terminator, CR , LF or CR

CR Carriage return, ASCII 0Dh

LF Line feed, ASCII 0Ah

### Calibration report using an external weight

Setting of " InFa | !" Setting of " InFa 2" AD-8121 printer format General format A & D \_\_\_\_A\_&\_D<TERM> Manufacturer -MC-100K MODEL\_\_\_MC-100K<TERM> MODEL Model SZN 01234567 S/N\_\_\_\_01234567<TERM> Serial number -ID I D\_\_\_\_ABCDEFG<TERM> **ABCDEF**6 ID number -DATE 2012/12/31 DATE<TERM> - Date TIME 12:34:56 \_\_\_\_2012/12/31<TERM> Time TI ME<TERM> CALIBRATED (EXT.) Calibration type CAL. WEIGHT \_\_\_\_12: 34: 56<TERM> +100000.0 CALIBRATED(EXT.)<TERM> Calibration weight SIGNATURE CAL. WEI GHT<TERM> Signature | \_\_\_+100000. O\_\_g<TERM> SI GNATURE<TERM> <TERM> <TERM> ----<TERM> <TERM> Space, ASCII 20h <TERM> <TERM> Terminator, CR, LF or CR Carriage return, ASCII 0Dh

### Calibration test report using an external weight

**Note** Calibration test does not perform calibration.


Line feed, ASCII 0Ah

Line feed, ASCII 0Ah

CR

LF

LF



### Title block and end block


When weight values are recorded as GLP data, a "Title block" is inserted at the beginning and an "End block" is inserted at the end of a group of weight values in the GLP report.

#### **Notes**

- □ To output the report to an AD-8121B, use MODE 3 of the AD-8121B.
- □ If the data memory function is used, the "Title block" and "End block" can not be output.

### **Operation**

- Step 1 With the weighing data displayed, press and hold the PRINT key, until 5tRrt is displayed, then release the key. The "Title block" is output.
- Step 2 The weighing data is output according to the parameter setting of the data output mode (P E) of the function table.
- Step 3 Press and hold the PRINT key until release the key. The "End block" is output.



□ Space, ASCII 20h

<TERM> Terminator, CR , LF or CR


CR Carriage return, ASCII 0Dh


LF Line feed, ASCII 0Ah

## 12. Standard Input And Output Interface

## 12-1. RS-232C and External Contact Input

### D-Sub 25 pin numbers





D-Sub 25 pin assignments

Pin No.	Signal name	Interface type	Direction	Description
1	FG		_	Frame ground
2	RXD	RS-232C	Input	Receive data
3	TXD	RS-232C	Output	Transmit data
4	RTS	RS-232C	Input	Ready to send
5	CTS	RS-232C	Output	Clear to send
6	DSR	RS-232C	Output	Data set ready
7	SG	RS-232C / external contact input	_	Signal ground
18	PRINT	External contact input	Input	Same as the PRINT key
19	RE-ZERO	External contact input	Input	Same as the RE-ZERO key
Others	_	<del>-</del>	_	No connection

### **RS-232C**

The balance is a DCE device. Connect the balance to a personal computer (DTE) using a straight through cable.

Transmission system : EIA RS-232C

Transmission form : Asynchronous, bi-directional, half duplex

Transmission rate : 10 times/second or 5 times/second (same as data refresh rate)

Data format : Baud rate : 600, 1200, 2400, 4800, 9600 bps

Data bits : 7 or 8 bits

Parity: Even, Odd (Data bits 7 bits)


None (Data bits 8 bits)

Stop bit : 1 bit


(When sending, 2 bits; receiving, 1 bit.

A personal computer will function with either setting.)

Code : ASCII




### **RS-232C Terminals**



### External contact input

By connecting pin 18 (PRINT command) to pin 7, or pin 19 (RE-ZERO command) to pin 7 for 100 ms or more, the same operation as performed by pressing the PRINT key or the RE-ZERO key, will be performed.


Example use of foot switch




### **Option**

Connector: AX-HDB-25P/CTF

Foot switch : AX-SW128





## 12-2. Connection to Peripheral Equipment

### 12–2–1. Connection to the AD–8121B Printer

Preset the following parameters to use the AD-8121B printer.

Class	Item and Parameter	Factory settings	AD-8121B MODE 1	AD-8121B MODE 2	AD-8121B MODE 3
	Pr է Data output mode	0	0, 1,2	3	0, 1,2
	유후-후 Auto print polarity	0	#1	Not	#1
	RP-Ь Auto print difference	0	#1	necessary	#1
dout	d-no Data number output	0	0	0	0, 1
Data output	5-とd Time/Date output	0	0	0	0, 1,2,3
	5- ਜ਼ੀ ID number output	0	0	0	۵,۱
	PUSE Data output pause	0	0	0	0,1 #2
	RE-F Auto feed	0	0	0	Ο, Ι
	6년5 Baud rate	2	2	2	2
5 ,F	ይይም Data bit, parity bit	0	0	0	0
Serial	ErLF Terminator	0	0	0	0
interface	는	0	0	0	1
	CTS, RTS control	0	0	0	0

<sup>#1</sup> Set parameters when auto print mode A or B ( $Prt \mid or 2$ ) is selected.

### Settings of AD-8121B

MODE	AD-8121B DIP switch	Description
MODE 1	D 1 2 3 4	Print at receiving data. Standard mode, statistic mode
MODE 2	MODE TO STATE OF THE PROPERTY	Print by DATA key operation or built-in timer. Standard mode, interval mode, chart mode
MODE 3	MODE 3 4	Print at receiving data. Dump print mode

DIP switch No.3: Handling unstable data

ON Print

OFF Not printed



DIP switch No.4 : Data input specifications (Interface selection)

ON Current loop OFF RS-232C





Setting	Output data
dafa 0	The weighing data
ARFB 5	The weighing data stored in memory
ARFB 3	The calibration report stored in memory

□ Refer to "11-2. GLP Report" for print samples.

<sup>#2</sup> Set / when multiple lines are printed. Example: When adding ID number, set /.

### 12-2-2. Connection to a Computer and the Use of WinCT

The balance is of the DCE type (Data Communication Equipment), which can be connected to a personal computer using the RS-232C interface. Before connection, read the personal computer manual thoroughly. Use a standard DCE cable for connection (cable type: straight-through). When the personal computer type is a DOS/V with a 9-pin port, use a straight-through cable with a 25-pin male connector and a 9-pin female connector.

### **Using Windows Communication Tools Software (WinCT)**

When Windows is used as an operating system in a personal computer, the WinCT software can be used to transmit the weighing data to the personal computer. The current version of the WinCT can be downloaded from the A&D website. Check for applicable Windows versions when downloading the software.

For details on WinCT, refer to the WinCT instruction manual which is available on the A&D website. The WinCT software has two communication methods: "RsCom" and "RsKey".

### **RsCom**

- RsCom can transmit commands to control the balance.
- RsCom can perform bi-directional communication between the balance and a personal computer using the RS-232C interface.
- RsCom can display or store the data using a text file format. RsCom can also print the data using a printer connected to the personal computer.
- When several ports of a personal computer have balances connected, can communicate with each balance simultaneously.
- RsCom can share a personal computer with other application software.
- RsCom can receive the balance GLP report.

### RsKey

- RsKey can transmit the weighing data output from the balance directly to other application software such as Microsoft Excel.
- RsKey can be used with most application software.
- RsKey can receive the balance GLP report.

### Using the WinCT software, the balance can do the following:

### Analyzing the weighing data and the statistics with "RsKey"

The weighing data can be input directly into an Excel worksheet. Then, Excel can analyze the data to obtain total, average, standard deviation, maximum and minimum value, and display them in a graph.

### Controlling the balance using commands from a personal computer

By using "RsCom", the personal computer sends commands such as "re-zero" or "send weighing data" to the balance and controls the balance.

### Printing the balance GLP report using your printer

The balance GLP report can be printed using a printer connected to the personal computer.

### Receiving weighing data at a certain interval

The weighing data can be received at a certain interval and data characteristic with elapsed time can be obtained.

### Using the balance memory function

The weighing data can be stored in the balance's memory and can be transmitted to a personal computer at one time.

### Using a personal computer as an external indicator

With the "RsKey" test mode function, a personal computer can be used as an external weight indicator for the balance. (To do this, set the balance data output mode to stream mode.)

## 13. Commands

## 13-1. Command List

Note A command has a terminator added, that is specified using "5 if [rlf" of the function table, and is sent to the balance.

Commands to quer	Commands to query weighing data							
С	Cancels the S or SIR command.							
Q	Requests the weighing data immediately.							
S	Requests the weighing data when stabilized.							
SI	Requests the weighing data immediately.							
SIR	Requests the weighing data continuously.							

Commands to contr	ol the balance						
?CN	Requests the code number of the selected upper/lower limit value.						
?HI	Requests the upper limit value.						
?ID	Requests the ID number.						
?LO	Requests the lower limit value.						
?MA	Outputs all weighing data in memory.						
?MQnnn	Outputs data with the data number nnn. nnn: Three digits						
?MX	Outputs the number of data in memory (the last data number)						
?PN	Request the code number of the selected tare value.						
?PT	Request the tare value.						
?SN	Request the serial number of the balance.						
?TN	Request the model name of the balance.						
?UN	Requests the code number of the selected unit mass.						
?UW	Requests the unit mass value.						
CAL	Same as the CAL key.						
CN:mm	Recalls the upper/lower limit value in memory. mm: Two digits						
	Sets the upper limit values is space mark.						
HI:*****	Example: the upper limit value is 20000.0 g.						
	Command: HI:+020000.0g						
ID:****	Sets the ID number.						
	Sets the lower limit values is space mark.						
LO:*****.*g	Example: the lower limit value is 1000.0 g.						
1/07	Command:LO:+001000.0g						
MCL	Deletes all data in memory.						
MD:nnn	Deletes data with the data number nnn. nnn: Three digits.						
OFF	Turns the display off.						
ON	Turns the display on.						
P	Same as the ON:OFF key						
PN:mm	Recalls the tare value in memory. mm: Two digits						
PRT	Same as the PRINT key						
B	Sets the tare value is space mark.						
PT:*****.*g	Example: the tare value is 10000.0 g.						
	Command:PT:+010000.0g						

Commands to contro	Commands to control the balance							
R	Same as the RE-ZERO key							
SMP	Same as the SAMPLE key.							
U	Same as the MODE key							
UN:mm	Recalls the unit mass values in memory. mm: Two digits							
	Changes the unit mass value. Unit "g" only is space mark.							
UW:*****.*g	Example: the unit mass value is 2000.0 g.							
	Command: UW: +002000.0പg							

When a unit is required in commands such as a "PT:" command, use the 3-digit unit code of the A&D standard format.

nnn indicates a three-digit numerical value.

## 13-2. Acknowledge Code and Error Codes

When the "Serial interface function  $(5 \, _{i}F)$ " parameter is set to " $E_{r}Ed \, _{i}F$ ", the balance outputs <AK> code or error code to each command as follows:

<AK> (06h) Acknowledge in ASCII code.

- When the balance receives a command to request data and can not process it, the balance transmits an error code (EC, Exx).
  - When the balance receives a command to request data and can process it, the balance outputs the data.
- $\Box$  When the balance receives a command to control the balance and can not process it, the balance transmits an error code (EC, Exx).
  - When the balance receives a command to control the balance and can process it, the balance transmits the acknowledge code.

Among commands to control the balance, the following transmit the acknowledge code both when the balance receives the command and when the balance has accomplished the command. If the command can not be processed properly, the balance transmits an error code (EC, Exx). This error can be cleared using the CAL command.

CAL command (Calibration command using internal mass)


ON command (Display ON command)

P command (Display ON/OFF command)

R command (RE-ZERO command)

xx is error code number.

#### R command



When a communication error has occurred due to external noise, or a parity error has occurred due to transmission error, the balance transmits an error code. In this case, send the command again.

## 13-3. Control Using CTS and RTS

Depending on the " $\{\xi \}$ " parameter of "Serial interface  $\{\xi \}$ ", the balance performs as follows:

### CES 0

Regardless of whether the balance can receive a command or not, the balance keeps the CTS line HI. The balance outputs data regardless of the condition of the RTS line.

### [ES 1

The CTS line is kept Hi normally. When the balance can not receive the next command (Example: while the balance is processing the last command), the balance sets the CTS line to Lo. The balance confirms the level of the RTS line before outputting a set of data. If the RTS level is Hi, the balance outputs data. If the RTS level is Lo, data is not output (The data is canceled).

### 13-4. Settings Related to RS-232C

Concerning the RS-232C, the balance has two functions: "Data output (dout)" and "Serial interface  $(5 \, ^{1}F)$ ". Set each function as necessary.

## 14. Extended Function

The MC series balance has several extended functions equipped for special applications or to troubleshoot when using the standard functions.

When the "Filter ( $F \not l l$ )" is set to " $\mathcal{Q}$ ", extra items are available as shown below.


Class	Item and Parame	ter		Description
	F I-b Averaging range for the first moving average	3 - 4	Small  Large	When the fluctuation of a weight value is within the averaging range, the averaging operation starts to stabilize the displayed value. When the fluctuation of a weight value is small, for example, when weighing or filling a small amount of sample, the averaging is always performed and the response rate maybe slow. Under such a condition, change the parameter. Refer to "Averaging range (F /-b) and averaging time (F /-b)"
ErFnc Extended function	F I-L Averaging time for the first moving average	0 - 2 - 3 - 4 - 5	No averaging 0.5 second 1.0 second 1.5 seconds 2.0 seconds 2.5 seconds 3.2 seconds	When the fluctuation of a weight value is within the averaging range, the averaging operation starts. Once the duration of averaging operations reach the averaging time, moving averaging starts. This parameter sets the time to start moving averaging.  Refer to "Averaging range (F 1-b) and averaging time (F 1-b)"
	F2-b Averaging range for the second moving average	0 - ! - ? - ? - ?	Small	Refer to "Filter depending on differences in the amount to deliver powdery and liquid material".
	F2-E Averaging time for the second moving average	- 5 - 5	No averaging 0.5 second 1.0 second 1.5 seconds 2.0 seconds 2.5 seconds 3.2 seconds	

<sup>• :</sup> Factory settings.

## 14-1. Description of "Averaging range" and "Averaging time"

## 14-1-1. Averaging Range ( $F \mid -b$ ) and Averaging Time ( $F \mid -b$ )

- 1. When the fluctuation of a weight value is beyond the range that is selected in "F I-b", the averaging operation is disabled and the display reflects the varying value.
- 2. Once the fluctuation becomes within the selected range, the averaging operation starts to stabilize the weight value.
- 3. The process of averaging increases. When the selected time is reached, moving averaging will be performed.



When a small amount of sample is weighed or is filled, the fluctuation of a weight value is too small to be beyond the selected range and the averaging operation is not disabled. Consequently moving averaging is always performed and it takes a longer time to reach the final weight value. Under such a situation, change the setting of "F |-b" to a smaller range. But please note that the smaller the range is, the more prone to external disturbance the value will become.

# 14-1-2. Filter Depending on Differences in the Amount to Deliver Powdery and Liquid Material

- When the weight value is not stable even without load fluctuations
  - $\Box$  Increase the averaging range for the first moving average parameter ( $F \vdash b$ ).
  - □ Increase the averaging time for the first moving average parameter (F /- Ł).
  - □ Strengthen the digital filter. (Increase the function setting "Condition ([and)" parameter.)
- When response is slow during full and medium flow
  - □ Decrease the averaging range for the first moving average parameter (F 1-b).
  - □ Weaken the digital filter. (Decrease the function setting "Condition ([□□□d])" parameter.)
- When response is slow during dribble flow
  - □ Decrease the averaging time for the first moving average parameter (F /- Ł).
  - □ Weaken the digital filter. (Decrease the function setting "Condition ([□□□d)" parameter.
- To increase stability without load fluctuations
  - □ Increase the averaging range for the second moving average parameter ( $F \supseteq -b$ ).
  - □ Increase the averaging time for the second moving average parameter (F2-Ł).

## 15. Maintenance

### 15-1. Treatment of the Balance


In normal use, the balance can be cleaned with water. But, keep the following precautions so that dust and water do not invade the balance.

Do not direct water pressure at the bottom of the balance.

Do not use powerful water jets.

Do not submerge the balance in water.

- Clean the balance with a lint free cloth that is moistened with warm water and a mild detergent.
- Do not use organic solvents to clean the balance.
- Do not disassemble the balance. Contact the local A&D dealer if the balance needs service or repair.
- Use the original packing material for transportation.
- While cleaning the balance and keeping it waterproof, attach the optional cover on the RS-232C serial interface terminal and cover the AC adapter jack.



## 16. Troubleshooting

## 16-1. Checking the Balance Performance and Environment

The balance is a precision instrument. When the operating environment or the operating method is inadequate, correct weighing can not be performed. Place a sample on the pan and remove it, and repeat this several times. if the balance seems to have a problem with repeatability or to perform improperly, check as described below. If improper performance persists after checking, contact the local A&D dealer for repair.

### Checking that the balance performs properly

- Check the balance performance using the self-check function as described in "7. Weighing Speed Adjustment / Self Check Function".
  - An error display appears when a malfunction is found.
- Check the balance repeatability using an external weight. Be sure to place the weight in the center of the weighing pan.
- Check the balance repeatability, linearity and calibrated value using external weights with a known value.

## Checking that the operating environment or weighing method is proper Operating environment

- Is the weighing table solid enough?
- Is the balance level? Refer to "3-1. Before Use".
- Is the operating environment free from vibration and drafts?
- Is there a strong electrical or magnetic noise source such as a motor near the balance?

### Weighing method

- Is the weighing pan installed correctly?
- Is the RE-ZERO key pressed before placing a sample on the weighing pan?
- Is the sample placed in the center of the weighing pan?
- Has the balance been calibrated using the internal mass (one-touch calibration)?
- Has the balance been warmed up for 30 minutes before weighing?

### Sample and container

- Has the sample absorbed or lost moisture due to the ambient conditions such as temperature and humidity?
- Has the temperature of the container been allowed to equalize to the ambient temperature?
   Refer to "3-2. During Use".
- □ Is the sample charged with static electricity? Refer to "3-2. During Use".
- Is the sample of magnetic material such as iron? Caution is required for weighing magnetic materials. Refer to "3-2. During Use".

## 16–2. Error Codes

Display	Error code	Description
Errorl	EC, E11	Stability error The balance can not stabilize due to an environmental problem. Check around the pan. Refer to "3. Precautions". Prevent vibration, drafts, temperature changes, static electricity and magnetic fields, from influencing the balance. To return to the weighing mode, press the CAL key.
Error?		Out of the setting range The data to be stored is out of the setting range.
Errorb	EC, E16	Internal mass error Applying the internal mass does not yield a change in the weight value as specified. Confirm that there is nothing on the pan and perform the weighing operation from the beginning again.
Errorl	EC, E17	Internal mass error The internal mass application mechanism does not function properly. Perform the weighing operation from the beginning again.
CAL E	EC, E20	Calibration weight error  The calibration weight is too heavy. Confirm the calibration weight value. Press the CAL key to return to the weighing mode.
-CAL E	EC, E21	Calibration weight error  The calibration weight is too light. Confirm the calibration weight value. Press the CAL key to return to the weighing mode.
E		Overload error  A sample beyond the balance weighing capacity has been placed on the pan. Remove the sample from the pan.
- E		Weighing pan Error The weight value is too light. Confirm that the weighing pan is properly installed. Press the ON:OFF key two times to return to the weighing mode. If the error still persists, calibrate the balance.
Lo		Sample mass error The balance can not store the sample for the counting mode or for the percent mode because it is too light. Use a larger sample.
25 - pc	25	Unit mass error The sample unit mass for the counting mode is too light. Storing and using it for counting will cause a counting error. Add samples to reach the specified number and press the PRINT key. Pressing the PRINT key without adding samples will shift the balance to the counting mode. But, to acquire accurate weighing, be sure to add samples.

ormed Press ormed
Press
ormed
ration
ration
ماء ماء
-check
k and
dapter
iently,
. J. 101y,
ed the
/ data.
emory
store
DATA
100 of
/pe of l nanual
idi idal
n the
11 UIC
sing a
y u

Display	Error code	Description
		Timeout error
	EC, E03	If the timeout parameter is set to "٤-٤١", the balance did not
	LO, L03	receive the next character of a command within the time limit
		of one second. Confirm the communication.
		Excess characters error
	EC, E04	The balance received excessive characters in a command.
		Confirm the command.
		Format error
		A command includes incorrect data.
EC, E06		Example:
		<ul> <li>The data is numerically incorrect.</li> </ul>
		Confirm the command.
		Parameter setting error
	EC, E07	The received data exceeds the range that the balance can
		accept. Confirm the parameter range of the command.
Other error code		If an error described above can not be cleared or other errors
Other end code		are displayed, contact the local A&D dealer.

## 16-3. Other Display



When this indicator blinks, automatic self calibration is required. The indicator blinks when the balance detects changes in ambient temperature. If the balance is not used for several minutes with this indicator blinking, the balance performs automatic self calibration. The blinking period depends on the operating environment.

Advise

The balance can be used while this indicator is blinking. We recommend that you perform automatic self calibration for precision weighing.

## 16-4. Asking for Repair

If the balance needs service or repair, contact your local A&D dealer.

The balance is a precision instrument. Use much care when handling the balance and observe the following when transporting the balance.

- Use the original packing material for transportation.
- Remove the weighing pan from the main unit before placing the balance in the shipping container.

## 17. Specifications


	MC-100KS			
Weighing capacity	101 kg			
Maximum display	101084.4 kg			
Minimum weighing value (1 digit)	0.1 g			
Repeatability *1	0.2 g / 100 kg to 60 kg			
(Standard deviation)	0.1 g / less than 60 kg			
Linearity*1	±2.4 g			
Sensitivity drift, (10°C ~ 30°C / 50°F ~ 86°F, when automatic self calibration is not used)	±6 ppm/°C			
Accuracy immediately after calibration using the internal mass *2 (Accuracy of full scale)	±10.0 g			
Operating environment	5°C to 40°C (41°F to 104°F)			
Operating environment	85%RH or less (No condensation)			
Internal mass	Built-in function			
Time and clock function	Built-in function			
Display refresh rate	Approx. 5 times/second or 10 times/second			
Display mode	g (gram)			
Interface (Provided as standard)	RS-232C			
External calibration weight	60 kg, 80 kg, 100 kg			
Weighing pan	386 x 346 mm			
	Display: 260(W) x 164(D) x 202(H) mm			
External dimensions	Main unit: 346(W) x 443(D) x 130(H) mm			
	Cable length: 3 m			
Weight	Approx. 18 kg			
	Power consumption:			
Power supply (AC adapter)	Approx. 15 VA (supplied to the AC adapter)			
, , , , , , , , , , , , , , , , , , , ,	Confirm that the adapter type is correct for the local			
	voltage and power receptacle type.			
Accuracy class M1	20 kg, 50 kg, 100 kg			
Dust and water protection	Complying with IP65			

<sup>\*1:</sup> When loading and unloading are performed at the same place using the automatic loading machine under good ambient conditions.

The value of the internal mass may change due to corrosion or other damage caused by the operating environment, or due to aging. Check the internal mass using an external weight periodically.

<sup>\*2:</sup> Accuracy immediately after calibration using the internal mass under good ambient conditions (within the temperature range of 10°C to 30°C (50°F to 86°F) with no abrupt changes in temperature or humidity, no drafts, no effect by magnetic fields or static electricity).

## 17-1. External Dimensions



Unit: mm

## 17-2. Options and Peripheral Instruments

### GP-04: Comparator Output (Relay/ with a Buzzer) / RS-232C / Current Loop

- □ This option generates a relay output corresponding to ℍ, ⋈ and ⋈ in the display.
- Current loop and RS-232C can be used at the same time.
   For example, a personal computer and an AD-8121B printer can be used simultaneously.
- □ This option is installed in place of the standard RS-232C serial interface.

### GP-06: Analog Voltage Output / Current Loop

- □ This option outputs a voltage of 0 to 1V (or 0.2 to 1V) depending on the displayed value.
- □ With this option, current loop can be used.
  - For example, an AD-8121B printer can be used simultaneously using this option.
- □ This option is installed in place of the standard RS-232C serial interface. So, RS-232C is not available for use.
  - **Note** When option GP-04 or GP-06 is installed in the balance, the balance does not comply with IP-65 (waterproof and dustproof).

## GP-07: Extension Cable, 5 m (Available as factory option only when ordered with an MC-100KS balance)

 A cable of 5 meters, to connect between the display and the main unit (The standard cable is 3 meters.)

### GP-12: Animal Weighing Bowl

- This bowl can be used to weigh a small animal.
- When using this bowl, the weighing range that can be used is an approximately 4 kg less than the weighing capacity.

### GP-21: Underhook

Used for measuring the density of magnetic materials and concrete (coarse aggregates).

#### GP-22: Printer Bracket

Used to place the AD-8121B printer beside the display

### AX-K01710-200: RS-232C Cable

Length 2 m, straight type, D-sub 9pin - D-sub 25pin.

#### AD-8121B: Printer

- Compact dot-matrix printer
- Statistical function, clock and calendar function, interval print function, graphic print function, dump print mode
- □ 5 x 7 dots, 16 characters per line
- Print paper (AX-PP143, 45 (W) x 50 (L) mm , ø65 mm)
- AC adapter or alkaline battery

### AD-1691: Weighing environment analyzer

- A tool to support various functions such as daily balance checks, uncertainty calculations and evaluations of the environment where the balance is installed.
- Being compact in size, can be carried to the balance installation site easily.
   One analyzer can manage several balances.

### AD-1687: Weighing Environment Logger

- A data logger equipped with 4 sensors for temperature, humidity, barometric pressure and vibration that can measure and store environmental data. When connected to the RS-232C interface of the balance, the AD-1687 can store environmental data along with weighing data. Therefore, it is possible to store data in an environment where a computer can not be used.
- The stored data can be read to a personal computer using USB.
   As the AD-1687 is recognized as USB memory, special software is not required to read the data.

### AD-1688: Data Logger

When connected to the RS-232C interface of the balance, the AD-1688 can store the data in an environment where a personal computer can not be used.

### AD-8526: Ethernet Converter

 Used to connect the RS-232C interface of the balance to the Ethernet (LAN) port of a computer. This allows management of the balance weighing data with a computer connected to a network.

### AD-8527: Quick USB Adapter

- No dedicated power supply required. / No software required.
- Transmits the weighing data to a personal computer in real time and inputs the data directly into applications such as Excel or Word.
- IP65 compliant

### AD-8920A: Remote Display

Can be connected to the balance using the RS-232C interface.

#### AD-8922A: Remote controller

- Can be connected to the balance using the RS-232C interface and can control the balance remotely.
- Various options such as comparator output or analog output are available.

### AX-USB-25P-EX: USB converter

- Adds a COM port to a PC.
- Enables bi-directional communication between the PC and the balance when a USB driver is installed.
- Can use serial communication software such as WinCT on a PC without COM ports.
- An RS-232C cable is provided to connect the USB converter to the balance.

### AD-1682: Rechargeable Battery

Allows use of the balance in a place where AC power is not available.

#### AX-SW128: Foot Switch

Connected to the connector (AX-HDB-25P), functions as the RE-ZERO key or PRINT key.

**Note** Before using the foot switch, connect the connector, the connector cover and the foot switch.

### AX-HDB-25P/CTF: Connector

- Consists of a connector (AX-HDB-25P) and a connector cover (AX-HDB-CTF).
- Creates a contact that functions in the same way as the RE-ZERO key or PRINT key.

## 18. Terms/Index

## 18-1. Terms

Calibration Adjustment of the balance so that it can weigh accurately.

Calibration weight A weight used for calibration

Data number 
Numbers assigned sequentially when weighing data or unit weight is

stored.

Digit The minimum weighing value available. Used for the balance, one digit

is the smallest mass that can be displayed.

Environment Ambient conditions such as vibration, drafts, temperature, static

electricity and magnetic fields which affect the weighing operation.

GLP Good Laboratory Practice

GMP Good Manufacturing Practice

Internal mass Built-in calibration weight

IP-65 IP code: Degree of protection provided by enclosures.

6: Dust-tight. No ingress of dust. 5: Protect against water jets.

Mode Balance operational function.

Output To output the weighing data using the RS-232C interface.

Repeatability Variation in measured values obtained when the same mass is placed

and removed repetitively. Usually expressed as a standard deviation. Example: Standard deviation = 1 digit: This means that measured values, obtained when the same sample is placed and removed

repetitively, fall within ±1 digit in the frequency of about 68%.

Re-zero To set the display to zero.

Sensitivity drift An affect that a change in temperature causes to the weighing data.

Expressed as a temperature coefficient.

Example: Temperature coefficient = 6 ppm/°C: If a load is 100 kg and the temperature changes by 10°C, the value displayed changes by the

following value.

0.0006%/°C x 10°C x 100 kg = 0.6 g

In this example, if the value displayed is 100000.0 g before

temperature changes, a temperature change of 10°C will make the

value displayed 100000.6 g.

Stable value The stable weight data, indicated by the illuminated stabilization

indicator.

Stabilization time Time required after a sample being placed, until the stabilization

indicator illuminates and the weighing data is displayed.

Store To save the weighing data, unit mass or calibration data using the data

memory function.

Tare To cancel the weight of a container which is not to be included in the

weighing data. Normally, refers to an operation of placing a container

and setting the display to zero.

Target weight An external weight used for calibration test

Zero point A weighing reference point. Usually refers to the value displayed when

nothing is on the weighing pan.

## 18-2. Index

Keys and	symbols		
CAL	CAL key11, 27	65Pr	Data bit, parity bit30, 44
MODE	MODE key11	- C -	
/Ċ ON:OFF	ON OFF key11	ERL	Automatic self calibration
Q PRINT	PRINT key11, 27	-CRL E CRL E	Calibration weight error54 Calibration weight error54
+0/T+ RE-ZERO	RE-ZERO key11, 27	ERL in	One-touch calibration 20
1/10d SAMPLE	SAMPLE key11, 27	[AL out	Calibration using an external weight 21
ANIMAL	Animal indicator11	Calibration Calibration	18, 22, 61 test
ANIMAL	Calibration will start11, 19		weight 18, 61
100	Capacity indicator11	[[ out	Calibration test22
, <b>8</b> (8(8)	Data number11	[H 0	Response error55
<b>V</b>	Interval memory mode11	[H nG [H no	Check NG
· ▼	Mode standby11	LK no [L AdJ	Check NO
	Process indicator11, 19	Γlr	Initializing the balance
ы	Space mark39, 40, 41		Memory type error55
0	Stabilization indicator11, 27	Lond	Condition14, 28, 32
<b>◄</b>	Standby indicator11	[P	Comparator mode28
RESPONSE FAST		[P Fnc [P Kı	Comparator28, 29
	3 3 1	[P in	Upper limit
		CP LAE	Tolerance
- A -		CP Lo	Lower limit
	ıt34	[P rEF	Reference value29
AC adapte Accessory	r59, 60	[P-P	Main display comparison
AD-1682	Rechargeable battery60	[P-r [r[F	Comparison results
AD-1687	Weighing environment logger60	[5 in	Internal mass correction31
AD-1688	Data logger60		t
AD-1691	Weighing environment analyzer59	[ Ł S	CTS, RTS control 30, 44
AD-8121B AD-8526	Printer59 Ethernet Converter60	CTS	48
AD-8520 AD-8527	Quick USB Adapter60	5	
	Remote display60	- <b>D -</b> JRER	Data mamany 20
AD-8922A	Remote controller14, 60		Data memory 29 er
Rdd	Accumulation function28	Digit	61
AK code 유무-占		d-no	Data number output30, 44
711 U Rr-d	Auto print difference 29, 33, 44 Zero after output30	dout	Data output29, 30, 33, 44
RP-P	Auto print polarity29, 33, 44	d5Fnc Dump print	Density function30
RL-F	Auto feed 30, 44	Dump piint	34
	range49, 50	-E-	
Averaging	time	-E E	Weighing pan Error54
AX-HDB-2	5P/CTF Connector43, 60 0-200 RS-232C Cable59	_	Overload error54
AX-SW128		EC,E00	Communications error55
AX-USB-2		EC,E01 EC,E02	Undefined command error 55
		EC,E02 EC,E03	Not ready 55 Timeout error 56
- <b>B</b> -	<b>-</b>	EC,E04	Excess characters error 56
685Fnc 6EP_	Environment display28	EC,E06	Format error 56
667_ 669-	LO buzzer29 OK buzzer29	EC,E07	Parameter setting error 56
6EP-	HI buzzer29	EC,E11	Stability error
6P5	Baud rate 30, 44	EC,E16 EC,E17	Internal mass error54 Internal mass error54
		, / /	moniai mass ciroi

EC,E20	Calibration weight error54	- N -		
EC,E21	Calibration weight error54	Numerical 1	format	35
Er[d	AK, Error code30			
Erfnc	Extended function 31, 49	-0-		
Error I	Stability error54	Option		50
Error 2	Out of the setting range54	Ориоп		00
Error 6	Internal mass error54	ъ		
Error 7	Internal mass error54	- <b>P</b> -		
Error code	54	P5.	internal mass correction	
	ınctions49	PnE_	Decimal point	28
	ight 18, 61	Poff	Auto display-OFF	28
LAIGITIAI WE	ignt 10, 01	P-on	Auto display-ON	28
_		PrE	Data output mode29, 33	3, 44
- F -	04.40	P-Er	Zero upon power-on15, 28	8, 32
F 1-6	31, 49	PUSE	Data output pause30	
F  - E	31, 49			•
F2-6	31, 49	- R -		
F2-E	31, 49	rĒcEnd	End block	/11
FAST	16		ty	
F IL	Filter 14, 28	Re-zero	ıty	01
FUL	Memory full55	r n li	Display at atom	01
	,		Display at start	40
- G -		RsCom		
GP-04	Comparator output/RS-232C/Current loop59	RsKey		45
GP-06		rtc PF	Clock battery error	55
GP-07	Analog voltage output/Current loop59	RTS		48
	Extension cable59			
GP-12	Animal weighting bowl59	- S -		
GP-21	Underfook59	5- ıd	ID number output30	0. 44
GP-22	Printer bracket59	5 iF	Serial interface	o. 44
65 i	Capacity indicator28	SLOW		
		5Pd	Display refresh rate	28
- H -		5Pn	Span calibration15, 28	<u>2</u> 0
HoLd	Hold function28		n time	5, 62 62
			e	
- -		Stable valu	Title block	
.d	ID number setting31	5E-6	Ctability band width 29	<del>1</del> เ
ID Number	32	5-69	Stability band width	
into	38 CL P output 30		Time/Date output30	
int	GLP output30 Interval time29	Store		62
		_		
	ss18	- T -		
IP-65	8, 59, 61	Tare		
		Target weig	يht1 ا	8, 62
- K -		Erc	Zero tracking	28
KF format	35	Ł-UP	Timeout	30
		E YPE	Data format 30	
- L -				•
Ldin	Liquid density input30	- U -		
Lo	Sample mass error54	- <b>0</b> - Ип 16	Unit	21
	Tampio mado onorminamo t	טיו ונ	Orat	J I
- M -		- W -		
	arator14, 28	WinCT	Communication Tools Software	15
	16	VVIIIOI	Communication 10018 Contware.	<del>1</del> 3
MID. nL t	Programmable-unit (Multi-unit)31	7		
Mode	61	- Z -		00
MT format	35	∠ero point		62
ivi i iuiiilat	ამ			



### A&D Company, Limited

3-23-14 Higashi-Ikebukuro, Toshima-ku, Tokyo 170-0013, JAPAN Telephone: [81] (3) 5391-6132 Fax: [81] (3) 5391-6148

### **A&D ENGINEERING, INC.**

1756 Automation Parkway, San Jose, California 95131, U.S.A. Telephone: [1] (408) 263-5333 Fax: [1] (408)263-0119

#### **A&D INSTRUMENTS LIMITED**

Unit 24/26 Blacklands Way, Abingdon Business Park, Abingdon, Oxfordshire OX14 1DY United Kingdom Telephone: [44] (1235) 550420 Fax: [44] (1235) 550485

#### **A&D AUSTRALASIA PTY LTD**

32 Dew Street, Thebarton, South Australia 5031, AUSTRALIA Telephone: [61] (8) 8301-8100 Fax: [61] (8) 8352-7409

#### A&D KOREA Limited

한국에이.엔.디(주)

서울특별시 영등포구 국제금융로6길33 (여의도동) 맨하탄빌딩 817 우편 번호 150-749 (817, Manhattan Bldg., 33. Gukjegeumyung-ro 6-gil, Yeongdeungpo-gu, Seoul, 150-749 Korea ) 전화: [82] (2) 780-4101 팩스: [82] (2) 782-4280

## OOO A&D RUS

### ООО "ЭЙ энд ДИ РУС"

121357, Российская Федерация, г.Москва, ул. Верейская, дом 17 (Business-Center "Vereyskaya Plaza-2" 121357, Russian Federation, Moscow, Vereyskaya Street 17 ) тел.: [7] (495) 937-33-44 факс: [7] (495) 937-55-66

ऐ&डी इन्स्ट्रयमेन्ट्स इण्डिया प्रा0 लिमिटेड

**A&D INSTRUMENTS INDIA PRIVATE LIMITED** 509, उद्योग विहार , फेस -5, गुड़गांव - 122016, हरियाणा , भारत

( 509, Udyog Vihar, Phase-V, Gurgaon - 122 016, Haryana, India ) फोन : 91-124-4715555 फैक्स : 91-124-4715599

## About the MC series balance function settings

### ☐ Factory settings have been changed for stable weighing

The factory settings described on page 31 of the MC series instruction manual have been changed.

The MC series are high resolution balances. Therefore, external disturbances such as breezes or vibrations may cause unstable weighing values.

For stable weighing, the factory settings of the following functions have been changed to those more resistant to external disturbances, as shown below.

### **New factory settings**

Class	Item and Parameter		er	Description
bASFnc	[ond	Condition	<b>-</b> 2	Slow response rate, stable value "SLOW"
Environment Display	FiL	Filter	<b>-</b> /	Used


Note: When the balance initialization is performed, the function settings will be changed as shown below. After initialization, confirm that the settings are appropriate before weighing.

#### Settings after initialization

Class	Item and Parameter			Description
bASFnc	Cond	Condition	1	"MID."
Environment Display	FiL	Filter	0	Not used

#### ☐ For stable weighing

When weighing values are unstable even with the functions set to those more resistant to external disturbances (" $\Gamma$  and" to " $\Gamma$ " and " $\Gamma$ " to " $\Gamma$ ", use the AD-1672 Tabletop Breeze Break to protect the balance from breezes.



Usage example: AD-1672 Tabletop Breeze Break and MC-1000 Balance