

# **EB SERVICE MANUAL**



# < Table of Contents >

1.	In	troductio	n	4
	1.1.	Preface.		4
	1.2.	Precauti	on	4
	1.3.	Specifica	itions	5
	1.4.	Dimensio	on	6
	1.5.	Key & SY	MBOLS ON DISPLAY	7
	1.6.	Sealing I	Method	9
2.	Ca	libration		.1
	2.1.	General	Calibration1	.1
	2.1	1.1. C	4 Setting	2
		2.1.1.1.	C4-1 Setting1	2
		2.1.1.2.	C4-2 Setting1	2
		2.1.1.3.	C4-3 Setting1	2
		2.1.1.4.	C4-4 Setting1	3
		2.1.1.5.	C4-5 Setting1	3
	2.1	1.2. S	PAN Calibration Setting (C-3)1	4
	2.1	1.3. 0	Fravity Constant Value Setting (C-9) 1	4
	2.1	1.4. C	alibration factor Setting (C-10)1	5
	2.1	1.5. C	Displaying Real A/D Value (C-5) 1	5
	2.1	1.6. I	nput Function Key Code (C-6)1	.6
	2.1	1.7. P	Percent Calibration (C-7)1	7
	2.1	1.8. B	attery Calibration (C-8)1	7
3.	Th	ne Schema	atics and Diagram1	.8
	3.1.	System I	Block Diagram1	.8
	3.2.	Circuit D	iagram1	9
	3.2	2.1. N	lain and Power1	.9
	3.2	2.2. C	Display part2	20
	3.2	2.3. K	Xey Part 2	1
4.	Ex	ploded V	iew2	2
5.	Lo	ad Cell di	rawing2	:3
6.	Pa	art Locatio	on2	4
	6.1.	Main PC	З (Тор) 2	4
	6.2.	Main PC	3 (Bottom) 2	25
	6.3.	Rear Dis	play PCB (Top)2	6



	6.4.	Rear Display PCB (Bottom)	26
	6.5.	Terminal PCB (Top)	27
	6.6.	Terminal PCB (Bottom)	27
	6.7.	Cal PCB (Top)	28
7.	E	rror Messages & Solution	29
8.	P	art List	30



# 1. Introduction

#### 1.1. Preface

Thank you for purchasing of our CAS scale.

This scale has been designed with CAS reliability, under rigid quality control and with outstanding performance.

WE hope that your departments enjoy with high quality of CAS product.

This manual will help you with proper operations and care of the EB series. Please keep it handy for the future references.

## 1.2. Precaution

- Make sure that you plug your scale into the proper power outlet.
- Place the scale on a flat and stable surface.
- Plug into a power outlet 30 minutes before operations.
- Keep the scale away from strong EMI noises may cause incorrect weight readings.
- This scale must be installed in a dry and liquid free environment.
- Do not subject the scale to sudden temperature changes.
- Do not subject the platter to sudden shocks.
- If the scale is not properly level, please adjust the 4 legs at the bottom of the scale (turn legs clockwise or counterclockwise) so as to center the bubble of the leveling gauge inside the indicated circle.



# 1.3. Specifications

	EB -60	EB-150			
Capacity / e	60 kg / 0.02 kg	150 kg / 0.5 kg			
Internal	1 / 60,000	1 / 60,000			
External	1/3,000 (Dual)	1/3,000 (Dual)			
Tare	29.99 Kg	59.98 Kg			
Display	Weight(6), unit pr	ice(6), total price(6)			
Indicators	STABLE, ZER	O, NET, Battery			
Keys	Number(0~9, 00), Clear, ZE Battery, BL, X, -(cancel), +(add)	RO, TARE, PLU Save, PLU Call, ), SUM(TTP), Mode, Power ON/OFF			
Functions	<ul> <li>Direct PLU(24) / Indirect PLU(200)</li> <li>Price computing scale</li> <li>Low Battery Indication function</li> <li>Auto Power Off, Auto BL off</li> <li>Beep Sound Off Function</li> </ul>				
Weight	ight 15kg				
Power	6V 5 Ah Pb Battery or 9 V Adaptor				
Op.Temperature	- 10 °C ~ +40 °C				
Options	Rear Display, Stainless-tray, Adaptor, RS232				
Minimum Voltage Level The Battery	About 5.7V				
Operation time About 200HR					



### 1.4. Dimension





# 1.5. Key & SYMBOLS ON DISPLAY

SYMBOLS	DESCRIPTION
►0<	To adjust zero
Z	Stable status
NET	Tare on
÷	Charge status
	Display battery status
¢	Back Light On status

KEYS	FUNCTIONS
0~9,00	To input all of numerical data
	Direct PLU keys (24EA)
Ċ	To save PLU
	To call up PLU

7



GURPUKATIUN	EB Service Manual				
C	To clear data				
► <b>0</b> ◄	To set zero				
►T<	To set or clear tare value				
Q	To turn on & off the scale				
¢	To turn on & off the backlight				
•772	Display battery voltage(%)				
+	To make several sales transaction by adding up				
—	To make discount transaction				
×	To multiply the same item when making sales transaction				
Σ	To check total sales amount or finalize sales transaction				
*	To soft key				

8



## 1.6. Sealing Method

### [PLATE]







10



# 2. Calibration

## 2.1. General Calibration

Pressing and holding calibration switch press [POWER] key to go to calibration mode.

User can move to other mode by using [ZERO] key in the calibration mode.

User also moves to other sub-modes for each mode by using [TARE] key.

Please simply follow below procedure to move to other mode.

- (1) Calibration Mode: Pressing and holding "Calibration Switch" press [POWER] key.
- (2) It displays "CAL-0" after "CAL", and it blinks the version of scale three times.
- (3) Selecting menu: press [TARE].
- (4) ENTER(Setting) : [TARE] key

MODE	Function			
CAL 1	Display normalized AD			
CAL 2	Display Keypad infomation-			
	Weight Setting Mode			
	"UnLoad" $\rightarrow$ [TARE] $\rightarrow$			
CAL 3	"MIDD" $\rightarrow$ [TARE] after loading for 1/3 weight $\rightarrow$			
	"FULL" $\rightarrow$ [TARE] after loading for Full weight $\rightarrow$			
	"MIDD" $\rightarrow$ [TARE] after loading for 1/3 weight $\rightarrow$ "END"			
CAL 4	Option Setting ( Table 1 참조 )			
CAL 5	Display filtered Raw AD			
CAL 6	Function setting on each Key(Table 2 참조)			
CAL 7	% Calibration			
CAL 8	Battery calibration			
CAL 9	Gravity constant			
	Set calibration factor			
	"Unit" $\rightarrow$ [TARE] $\rightarrow$ select 0, 1 (0:kg, 1: lb) $\rightarrow$ [TARE]			
	"CAPA" $\rightarrow$ [TARE] $\rightarrow$ select capacity $\rightarrow$ [TARE]			
CAL 10	"MCAPA" $\rightarrow$ [TARE] $\rightarrow$ select mid-capacity $\rightarrow$ [TARE]			
	"W-dP" $\rightarrow$ [TARE] $\rightarrow$ Select Decimal Point $\rightarrow$ [TARE]			
	" 1 d " → [TARE] → Select division → [TARE]			
	"Dual" $\rightarrow$ [TARE] $\rightarrow$ Enable dual interval (0:disable, 1:enable) $\rightarrow$ TARE			
CAL 11	Set nation(00 : OIML , 01 : NTEP , 02: KOREA)			



< Modes >

### 2.1.1.C4 Setting

#### C4-1 Setting 2.1.1.1.

	Initial Zero range	3	5%
DIT 67		2	10%
BIL 0~7		1	3%
		0	2%
PIT5	Tare Type	0	Proper tare
5110		1	Full Tare
BIT4			
	Successive tare	3	(+), (-) Direction successive Tare
		2	(-) Direction successive Tare
BIT 2~3		1	(+) Direction successive Tare
		0	One Time tare
BIT1			
BITO			

2.1.1.2. C4-2 Setting

BIT7			
BIT6	Use PLU Tare	1	Use
DITE	Use PLU Name	0	Don't use
ытэ		1	Use
DIT 4	Use Daily Total	0	Don't use
DIT4		1	Use
DIT3	Clear Price	0	Don't clear
		1	Clear
BIT 2	Clear Tare	0	Don't clear
		1	Clear
DIT1	Use Euro	0	Don't use
		1	Use
RITO	Power On Euro	0	No
		1	Yes

#### 2.1.1.3. C4-3 Setting

DIT 7	Dot Type	0	"." dot
		1	"," comma
BIT6	Use Preset tare	0	Don't use



		1	Use
DIT5	Use Back light	0	Don't use
ЫТЈ		1	Use
DIT 4	Use Head message	0	Don't use
DIT4		1	Use
	Use gram	0	Don't clear
ЫТЭ		1	Clear
	Use oz	0	Don't clear
DITZ		1	Clear
DIT1	Use Ib	0	Don't use
DITT		1	Use
RITO		0	No
ыто	Use Ny	1	Yes

÷

2.1.1.4. C4-4 Setting

BIT7	Х		
BIT6	Х		
	Price round off	3	00, 25, 50, 75
		2	00, 10, 20
DII 4~5		1	0, 5
		0	normal
BIT3	Х		
BIT2	Х		
	Unit / Price	3	1000/1
		2	100/1
0110~1		1	10/1
		0	1/1

#### 2.1.1.5. C4-5 Setting

BIT7	Use Standby time	0	Don't use
		1	Use
BIT6	Price decimal point	7	Special case
		6	0.00000
		5	0.00000



		4	0.0000
		3	0.000
		2	0.00
		1	0.0
		0	0
BIT3	Use Unit message	0	Don't use
		1	Use
BIT2			
	Print type	3	Don't use
BIT 0~1		2	DEP-50
		1	
		0	

### 2.1.2. SPAN Calibration Setting (C-3)

(1) Pressing and holding "Calibration Switch" press [POWER] key.

After "CAL" message blinks three times and shows the version of scale, it displays "CAL 1" message.

- (2) Press [ZERO] to display "CAL-3".
- (3) Press [TARE] key and then it displays "zero" message.
- (4) Press [TARE] key and then it displays "midup" message
- (5) Load middle weight (ex:1/3 full capacity) on the platform
- (6) Press [TARE] key and then it displays "span " message
- (7) Load full weight on the platform
- (8) Press [TARE] key and then it displays "middn" message
- (9) Load middle weight (ex:1/3 full capacity) on the platform
- (10) Press [TARE] key and then it display "CAL 3" message

#### 2.1.3. Gravity Constant Value Setting (C-9)

Current gravitational Acceleration value is set to  $9.7994 \text{ m/s}^2$ .

(1) Pressing and holding "Calibration Switch" press [POWER] key.

After "CAL" message blinks three times and shows the version of scale, it displays "CAL-1" message.

(2) Press [ZERO] to display "C-9".



- (3) Press [TARE] key, and then "G-1" message and "9.7994" will be shown. The first digit,"9" will blink.
- (4) Input a gravitational acceleration value by using [ZERO] key.
- (5) Press [TARE] key, and then "G-2" message blinks."9.7994" will be shown. The first digit,"9" will blink.
- (6) Input a gravitational acceleration value by using [ZERO] key.
- (7) Press [TARE] key to save the gravitational acceleration value, and "C-9" message will be shown.

#### 2.1.4. Calibration factor Setting (C-10)

- (1) Pressing and holding "Calibration Switch" press [POWER] key.
- (2) After "CAL" message blinks three times and shows the version of scale, it displays "CAL-1" message.
- (3) Press [ZERO] to display "C-10".
- (4) Press [TARE] key, and then "UNIT " message and "0" will be shown. The first digit,"0" will blink. It means calibration unit is "kg" (0 : kg, 1 : lb)
- (5) Input a calibration unit by using [ZERO] key.
- (6) Press [TARE] key, and then "CAPA" message blinks."0015" will be shown. The first digit,"0" will blink. It means a full-capability is "15 (calibration unit, kg or lb)"
- (7) Input a capability by using [ZERO] key.
- (8) Press [TARE] key, and then "MCAPA" message blinks."0005" will be shown. The first digit,"0" will blink. It means a mid-capability is "05 (calibration unit, kg or lb)"
- (9) Input a capability by using [ZERO] key.

(10)Press [TARE] key, and then "W-dP" message blinks."3" will be shown. The first digit,"3" will blink. It means a weight decimal point is "3 (will display 0.000)"

- (11)Input a weight decimal point by using [ZERO] key.
- (12) Press [TARE] key, and then "1d " message blinks."0.005" will be shown. The third digit,"0" will blink. It means a division is "0.005 (calibration unit, kg or lb)"
- (13) Input a division by using [ZERO] key.
- (14) Press [TARE] key, and then "dual " message blinks."1" will be shown. The third digit,"1" will blink. It means a dual interval is disable. (0 : disable, 1 : enable)"
- (15) Input a dual interval enable by using [ZERO] key.
- (16) Press [TARE] key to save the calibration factor, and "C-10" message will be shown.

#### 2.1.5. Displaying Real A/D Value (C-5)

Display Raw AD





#### 2.1.6. Input Function Key Code (C-6)

- (1) Under the calibration switch ON press [POWER] key.
- > "CAL" message blinks three times.
- (2) Press [ZERO] to display "C-6".
- (3) "E-SET" display on the weight window.
- (4) "XX" message shows up on the total price window.
- (5) Input "Soft Key Code" in the following table.

For first example, press '16' as SOFT KEY CODE and then press '+' key.

For second example, press '19' as SOFT KEY CODE and then ' $\Sigma^\prime$  key.

(5) Press 'C' key to exit from "Input Soft Key Code" mode.

• NOTE: User doesn't need MATRIX KEY CODES by inputting soft key code because MATRIX KEY CODES are fixed in hardware.

#### \* FIXED KEYS & THEIR SOFT KEY CODES

KEYS	MATRIX KEY CODES	SOFT KEY CODES
"0" through "9"	0 through 9	0 through 9
"C"	10	10
"ON/OFF"	12	12
"ZERO"	13	13
"TARE"	14	14

#### \* CHANGEABLE KEYS & SOFT KEY CODES

FUNCTION	SOFT KEY CODES	REMARK
"00"	11	
ADD	16	
TTP CALL	18	
PAY	19	
MR	20	
MW	21	
CAN	22	
MODE	23	
1/2	24	
1/4	61	25
PRE PACK	26	

KG/LB	27	
TEST	28	
HOLD	29	
PRINT	30	
NO FUNCTION	31	
EURO	60	
PERSENT TARE	62	
TARE SAVE	63	
BOTH SAVE	64	
PERSET	65	
MUL "X"	66	
PLU	32~59	

#### 2.1.7. Percent Calibration (C-7)

(1) Pressing and holding "Calibration Switch" press [POWER] key.

After "CAL" message blinks three times and shows the version of scale, it displays "CAL 1" message.

- (2) Press [ZERO] to display "CAL-7".
- (3) Press [TARE] key and then it displays "per 0" message. Select the percent value using the [numeric] key. You can choose 10~90 percent.
- (4) Press [TARE] key and then it displays "zero" message
- (5) Press [TARE] key and then it displays "pspan" message
- (6) Load choice percentage weight of full weight on the platform
- (7) Press [TARE] key and then it displays "CAL 7" message

#### 2.1.8. Battery Calibration (C-8)

- Pressing and holding "Calibration Switch" press [POWER] key. After "CAL" message blinks three times and shows the version of scale, it displays "CAL 1" message.
- (2) Press [ZERO] to display "CAL-8".
- (3) Press [TARE] key and then it displays voltage of battery.
- (4) Change the jumper-pin of main PCB, 'BAT' to '+ 5V'.
- (5) Press [ZERO] key two times and then Press [-] key two times.And then it display '500'
- (6) Change the jumper-pin of main PCB, '+ 5V' to 'BAT'.
- (7) You can see the calibrated voltage of battery.



# 3. The Schematics and Diagram

## 3.1. System Block Diagram

EB





3.2. Circuit Diagram

#### 3.2.1. Main and Power





#### 3.2.2. Display part

Q Q Q U2 +5V 1900 5 100 5 
 10
 CS
 1

 40
 MC
 MC

 50
 WR
 MC

 6
 DATA
 0

 8
 OSCI
 WR

 10
 IRO
 VDD

 X
 10
 VD

 X
 12
 BZ

 X
 16
 T2

 V0
 17
 T3

 V0
 17
 T3

 V0
 16
 T2

 V0
 17
 T3

 V0
 17
 T2
 51 50 49 48 48 LCD CS LCD RD LCD WR LCD DATA SEG19 EG18 EG17 EG16 C19 \_\_\_\_\_ 0.1u HT1622-64 QFP -0 SEG8 SEG7 COM0 COM1 2 2-2 2 2 2 2 2 3 3 3 

# SEG0 SEG1 SEG2 SEG3 SEG4 SEG5 COM0 COM2 COM3 COM4 COM5 COM6 COM7 SEG6 SEG7 SEG8 S0 -S1 -S3 -S3 -S5 -COM0 -COM1 -COM2 -COM3 -COM4 -COM4 -COM6 -COM7 -S6 -S7 -S8 -16 Weight\_DISPLAY SEG18 SEG19 SEG20 SEG22 SEG23 COM0 COM1 COM2 COM3 COM4 COM5 COM6 COM7 SEG25 SEG26 \$0 \$1 \$2 \$3 \$4 \$5 COM0 COM1 COM2 COM2 COM4 COM5 COM6 COM7 \$6 \$7 \$8 14 16 17 Total\_DISPLAY SEG9 \$0 \$1 \$2 \$3 \$4 \$5 COM0 COM1 COM2 COM2 COM4 COM5 COM6 COM7 \$6 \$7 \$8 SEG14 COM0 COM0 COM1 COM2 COM3 COM4 COM5 COM6 COM7 SEG15 SEG16 SEG17 8 12 13 14 15 16 17

**EB Service Manual** 



2007/06/13



20



#### 3.2.3. Key Part







# 4. Exploded View





# 5. Load Cell drawing



23



# 6. Part Location

# 6.1. Main PCB (Top)



24



## 6.2. Main PCB (Bottom)





# 6.3. Rear Display PCB (Top)



6.4. Rear Display PCB (Bottom)





# 6.5. Terminal PCB (Top)



# 6.6. Terminal PCB (Bottom)





6.7. Cal PCB (Top)





# 7. Error Messages & Solution

Error Message on Display	Description	Solution
"Frr 1"	The "Err 1" occurs when a current zero point has	Please call your CAS
	shifted from the last span calibration.	dealer.
"Err 2"	The "Err 2" is not a real error. Only it prompts return	Please call your CAS
	CAL switch to the normal position.	dealer.
"Err 10"	The "Err 10" means a failure of the analog module.	Please call your CAS
	Replace the analog module by a new one.	dealer.
	The "Err 11" means a writing error of the internal	
"[[ee 11]	nonvolatile memory. To recognize this error, be sure	Please call your CAS
"Err 11"	to check the voltage on the circuit and do calibration	dealer.
	procedures.	
	The "Err 12" warns that the scale has lost the	
"Err 12"	parameters for weighing regulations or has lost the	dealar
	factors for a digital span calculation.	
"Err 10"	The "Frr 12" means the soft key and is broken	Please call your CAS
	The En 13 means the soft key code is broken.	dealer.
"Holp 1"	"Holp 1" is marked in case of zero extent exceeded	Please remove the item
Перт	Thelp T is marked in case of zero extent exceeded.	from the platter.
"Holp 2"	"Help 3" is marked in case sale number of times	Spend again accumulated
Thep 5	exceeds 999 or add totalprice is over 9999.99	TTP value after delete
	- "Help 4" is marked in case Euro factor value is "0"	- Input again Euro factor
"Help 4"	at Euro rate application.	value.
	- "Help 4" Is marked when input smaller Pay cost	- Pay value than Total sale
Err 4"	than Total sale amount of money at Pay function	amount of money bigger
	use.	value or same value input
"Holp 5"	"Help 5" is marked when DTP number of times is	Spend again accumulated
	more than 50000 times.	DTP value after delete



# 8. Part List

	CODE	NAME	SPEC	Q'TY
1	7002Z0000000	PIEZO BUZZER	APR,ADR(CHINA)	1
2	7802CLL00030	CONNECTOR(WAFER)	LWL0640-03 (LSW250-03)	1
3	7805CCN67030	CONNECTOR(WAFER)	03–5267	2
4	7801CLW00050	CONNECTOR(WAFER)	LW0640-05(GOLD) (LPH01-05A)	1
5	7805CCN67020	CONNECTOR(WAFER)	02-5267	1
6	7804CCN73030	CONNECTOR(WAFER)	5273-03 (LPH03-03)	1
7		CONDENSER-ELECTRIC	470uF/35V(short type)	3
8	6712CHP01040	CONDENSER-CHIP	CL21F 104KBNC	11
9	6712CHP04710	CONDENSER-CHIP	470pF	1
10	6710CAP0103B	CONDENSER-CERAMIC	0.01uF/3KV	4
11	6704C1601000	CONDENSER-ELECTRIC	100u/16v	1
12	6294ICP01840	DIODE-CHIP	KDS184	2
13	6294ISW4148A	DIODE-SWITCHING	PMLL4148L(LP-CONT')	1
14	6291IS058190	DIODE POWER	1N5819(SMD)	4
15	6291IPO54060	DIODE-POWER	1N5406	1
16		DIODE-ZENER		1
17	6670T0001020	INDUCTANCE	HB-1M2012-102JT(TP2,LP2,DBB)	4
18	6670T0102200	INDUCTANCE	220uH(NT SERIES)	1
19	6810F0001020	FERRITE BEAD SMD ARRAY	MZA3216R102A(TDK)	2
20	628110016660	TRANSISTOR CHIP	KTA1666	1



#### **EB Service Manual** 628110022220 21 TRANSISTOR CHIP 2N2222AS 1 22 628110015040 KTA1504 SY TRANSISTOR CHIP 1 23 6527ID301000 **RESISTOR-CHIP 1/10W** RR1220P-103D(10K) 3 24 6598IJ301000 RP164P103J(=1608 10kΩ X 4PCS) **RESISTOR-CHIP-ARRAY** 25 0.33 2W **RESISTOR 2W** 1 26 6527ID300200 **RESISTOR-CHIP 1/10W** RR1220P-202D(2 kΩ) 1 27 6527ID300220 **RESISTOR-CHIP 1/10W** RR1220P-222D(2.2K) 1 28 6527ID300100 RESISTOR-CHIP 1/10W RR1220P-102D(1K) 2 29 6527ID310000 **RESISTOR-CHIP 1/10W** RR1220P-104D(100K) 6 30 6527ID300470 RR1220P-472D(4.7 kΩ) RESISTOR-CHIP 1/10W 1 6527ID010000 31 RESISTOR-CHIP 1/10W RR1220P-101D(100Ω) 1 32 RESISTOR-CHIP 1/10W 10Ω 1 33 MC34063A IC(step up-down regulator) 1 622410016220 34 IC(LCD DRIVER) HOLTEX HT1622 (ERS-LCD) 1 35 IC(REGULATOR) LM7809,KA7809 1 36 IC(INTERFACE) SP232ECY(SIPEX), MAX3232 1 6220IS0C5020 IC(REGULATOR) 37 XC6204C502MR(5.0V) 1 38 6236IS00245A IC(C MOS) 74HC245D(LP-II) 2 SOCKET CONNECTOR 39 7813C000050B 5332-50P 1 40 6710CAP0103B CONDENSER-CERAMIC 0.01uF/3KV 2 6271/0071800 SIDAC(VARISTOR) INR7D180(MW-2)-5EA 1 41