


















## TBWS Calibration Manual

1. Press  key during the self-checking after turning on the scale. Display will show "Pn".
2. Press , , and  to enter, the display will show "Po chk".
3. Press  until the display shows "p2 mod"
4. Once the display shows "p2 mod", open the display by unscrewing the screws and locate K3 on the mainboard. Upon locating, **press the button** to enter calibration mode (see the photo below).

5. Press  key to confirm and press  to select **single**
6. Press  key to confirm and press  to select **cap**.
7. Display will show the capacity weight. If you would like to change the calibration weight value, press  and  keys to change the active digits and press  key to increase the value.


8. When the calibration value is correct, press  key to confirm and press  to select **cal**.
9. Press  key to confirm

- 
10. Press  key to enter calibration, the display will show "unld". At this point, make sure there is no weight present on the scale.

11. When STABLE indicator shows, press  key to confirm.
12. Display will show the last calibration weight. If you would like to change the calibration weight value, press  and  keys to change the active digits and press  key to increase the value. (FYI. the calibration weight value needs to be at least 1/3 of the capacity weight; for example, insert the value of 150.0 to calibration weight if the capacity weight value is 500.0)

13. When the calibration value is correct, press  key to confirm. Then, the display will show "load". Place the calibration weight on the platform.

14. When the indicator becomes stable, press  key to confirm and the scale will return to normal weight mode.



**Press the calibration  
button in STEP 4.**